



- Other Property
  - Dozer Push
  - Contained Line
  - Clean Up Area
  - Wildfire Daily Fire Perimeter
  - Pump
  - Forest Service Land
  - Water Tank
  - State Public Lands
  - Aerial Hazard
  - Internet Access
  - Repeater
  - Other State Lands
  - Dip Site
  - HazTree Priority Roads
  - Check Point
  - Water Source
  - Helibase
  - Restricted Water Source
  - Sling Site
  - Unimproved Landing Area
  - Completed Dozer Line
  - Division Break
  - Completed Fuel Break
  - Incident Command Post
  - Completed Hand Line
  - Drop Point
  - Completed Mixed Construction Line
  - Staging Area
  - Completed Road as Line
  - Lookout
  - Planned Hand Line
  - Road Repair
  - Other
  - Repair Point
  - Repair Line
  - Landing or Log Deck
  - Road Repair
  - Fence - Cut/Damaged
  - Fire Edge
- Repair Status**
- Completed - Inspected
  - In Use - Fire Management
  - Completed - Ready for Inspection
  - In Progress
  - Repair Needed
  - No Repair Needed
  - Other - See Comments
  - Unknown

# Meyer Repair Area - Fallen Leaf

Caldor  
CA-ENF-24030  
October 19, 2021

