


- ⊙ Aerial Hazard
 - ⊙ Check Point
 - ⊙ Dip Site
 - ⊙ Sling Site
 - ⊙ Unimproved Landing Area
 - ⊙ Division Break
 - ⊙ Drop Point
 - ⊙ Staging Area
 - ⊙ Lookout
 - ⊙ Hot Spot - Spot Fire
 - ⊙ Value at Risk
 - ⊙ Other
- ⊙ Gate
 - ⊙ Bridge
 - ⊙ Water Development or Draft Site
 - ⊙ Structure Wrap
 - ⊙ Stream Crossing
 - ⊙ Road Repair
 - ⊙ Retardant in Avoidance Area
 - ⊙ Resource Location
 - ⊙ Repair Point
 - ⊙ Landing or Log Deck
 - ⊙ Fenced Tree
 - ⊙ Hazard - Cut/Damaged
- ⊙ Dozer Push
 - ⊙ Clean Up Area
 - ⊙ Mobile Weather Unit
 - ⊙ Repeater
 - ⊙ Hazard
 - ⊙ Water Source
 - ⊙ Restricted Water Source
 - ⊙ Completed Dozer Line
 - ⊙ Completed Fuel Break
 - ⊙ Completed Hand Line
 - ⊙ Completed Mixed Construction Line
- R - Completed Road as Line
 - H - Planned Hand Line
 - Access or Improved Road
 - Other
 - Repair Line
 - Road Repair
 - Retardant Drop
 - Route
 - Contained Line
 - HazTree PriorityRoads
 - Trail
- STATE
 - LOCAL
 - Repair Status
 - Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - Repair Needed
 - No Repair Needed
 - Other - See Comments
 - Unknown
 - Repair Areas

SUPPRESSION REPAIR

Caldor
 CA-ENF-24030
 October 21, 2021



REPAIR OVERVIEW
 Caldor
 CA-ENF-24030
 October 21, 2021