

# SUPPRESSION REPAIR


Caldor

CA-ENF-24030

October 23, 2021



REPAIR  
OVERVIEW  
Caldor  
CA-ENF-24030  
October 23, 2021



- ⊙ Aerial Hazard
- ⊙ Check Point
- ⊙ Dip Site
- ⊙ Sling Site
- ⊙ Unimproved Landing Area
- ⊙ Division Break
- ⊙ Drop Point
- ⊙ Staging Area
- ⊙ Lookout
- ⊙ Hot Spot - Spot Fire
- ⊙ Value at Risk
- ⊙ Other
- ⊙ Gate
- ⊙ Bridge
- ⊙ Water Development or Draft Site
- ⊙ Structure Wrap
- ⊙ Stream Crossing
- ⊙ Road Repair
- ⊙ Retardant in Avoidance Area
- ⊙ Resource Location
- ⊙ Repair Point
- ⊙ Landing or Log Deck
- ⊙ Hazard Tree
- ⊙ Fence - Cut/Damaged
- ⊙ Dozer Push
- ⊙ Clean Up Area
- ⊙ Mobile Weather Unit
- ⊙ Repeater
- ⊙ Water Source
- ⊙ Restricted Water Source
- ⊙ Completed Dozer Line
- ⊙ Completed Fuel Break
- ⊙ Completed Hand Line
- ⊙ Completed Mixed Construction Line
- ⊙ R - Completed Road as Line
- ⊙ H - Planned Hand Line
- ⊙ Access or Improved Road
- ⊙ Other
- ⊙ Contained Line
- ⊙ HazTree PriorityRoads
- ⊙ Trail
- ⊙ STATE
- ⊙ LOCAL
- ⊙ Repair Status
- ⊙ Completed - Inspected
- ⊙ Completed - Ready for Inspection
- ⊙ In Progress
- ⊙ Repair Needed
- ⊙ No Repair Needed
- ⊙ Other - See Comments
- ⊙ Unknown
- ⊙ Repair Areas

