



Feature/Category	Repair/Status	Count
Aerial Hazard	Unknown	1
Branch Break	Unknown	2
Bridge	No Repair Needed	8
Bridge	Other - See Comments	1
Bridge	Unknown	42
Camp	Unknown	7
Clean Up Area	Other - See Comments	1
Clean Up Area	Repair Needed	5
Culvert	Repair Needed	2
Culvert	Unknown	1
Dozer Push	No Repair Needed	22
Dozer Push	Repair Needed	19
Dozer Push	Unknown	19
Drop Point	No Repair Needed	2
Drop Point	Repair Needed	1
Drop Point	Unknown	45
Gate	No Repair Needed	13
Gate	Repair Needed	1
Gate	Unknown	327
Hazard Tree	Repair Needed	1
Hazard Tree	Unknown	1
Hellbase	Unknown	1
Hellspot	No Repair Needed	1
Hellspot	Repair Needed	1
Hellspot	Unknown	16
Landing or Log Deck	Repair Needed	1
Mobile Weather Unit	No Repair Needed	2
Mobile Weather Unit	Unknown	7
Other	No Repair Needed	2
Other	Other - See Comments	3
Other	Repair Needed	11
Repair Point	Other - See Comments	20
Repair Point	Repair Needed	4
Repair Point	Unknown	4
Resource Location	No Repair Needed	1
Resource Location	Repair Needed	3
Resource Location	Unknown	2
Restricted Water Source	No Repair Needed	2
Restricted Water Source	Unknown	2
Road Repair	Repair Needed	18
Road Repair	Unknown	2
Safety Zone	No Repair Needed	3
Safety Zone	Repair Needed	2
Safety Zone	Unknown	14
String Site	No Repair Needed	1
String Site	Unknown	3
Staging Area	Repair Needed	10
Staging Area	Unknown	6
Stream Crossing	No Repair Needed	1
Stream Crossing	Repair Needed	2
Stream Crossing	Unknown	10
Structure Wrap	Repair Needed	2
Structure Wrap	Unknown	1
Value at Risk	No Repair Needed	12
Value at Risk	Repair Needed	5
Value at Risk	Unknown	30
Water Development or Draft Site	Completed - Inspected	1
Water Development or Draft Site	In Use - Fire Management	1
Water Development or Draft Site	No Repair Needed	2
Water Development or Draft Site	Repair Needed	4
Water Development or Draft Site	Unknown	7
Water Source	No Repair Needed	16
Water Source	Repair Needed	3
Water Source	Unknown	76

Feature/Category	Repair Status	Count	Length (ft)	Length (mi)
Access or Improved Road	No Repair Needed	36	359,296	68.05
Access or Improved Road	Repair Needed	17	175,591	33.26
Access or Improved Road	Unknown	303	357,410	67.69
Completed Burnout	No Repair Needed	1	8,469	1.6
Completed Dozer Line	Completed - Inspected	1	1,211	0.23
Completed Dozer Line	No Repair Needed	6	10,502	1.99
Completed Dozer Line	Repair Needed	126	294,639	55.8
Completed Dozer Line	Unknown	78	183,498	34.75
Completed Fuel Break	Repair Needed	2	3,167	0.6
Completed Fuel Break	Unknown	1	6,498	1.23
Completed Hand Line	No Repair Needed	4	4,118	0.78
Completed Hand Line	Repair Needed	40	103,223	19.55
Completed Hand Line	Unknown	54	48,190	9.13
Completed Mixed Construction Line	Repair Needed	2	2,973	0.56
Completed Mixed Construction Line	Unknown	1	6,165	1.17
Completed Road as Line	No Repair Needed	8	124,094	23.5
Completed Road as Line	Repair Needed	29	155,083	29.49
Completed Road as Line	Unknown	52	56,365	10.65
Contained Line	Unknown	47	1,480,893	280.47
Fire Edge	Unknown	100	1,269,032	240.35
Planned Dozer Line	Unknown	17	157,414	29.81
Planned Hand Line	Unknown	17	15,416	2.93
Planned Mixed Construction Line	No Repair Needed	1	1,487	0.28
Planned Mixed Construction Line	Unknown	8	134,382	25.45
Planned Road as Line	Unknown	12	210,383	39.85
Repair Line	Repair Needed	1	3,151	0.6
Retardant Drop	No Repair Needed	4	2,692	0.51
Retardant Drop	Unknown	2	8,471	1.6

<ul style="list-style-type: none"> Fire Edge Contained Line Completed Burnout Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line Planned Dozer Line Planned Hand Line 	<ul style="list-style-type: none"> Planned Mixed Construction Line Planned Road as Line Access or Improved Road Repair Line Retardant Drop Aerial Hazard Check Point Head Repair Hellbase 	<ul style="list-style-type: none"> Division Break Drop Point Closure Camp Staging Area Lookout Hot Spot - Spot Fire 	<ul style="list-style-type: none"> Value at Risk Other Landmark Gate Bridge Water Development or Draft Site Structure Wrap Stream Crossing Road Repair Resource Location 	<ul style="list-style-type: none"> Repair Point Landing or Log Deck Hazard Tree Dozer Push Culvert Clean Up Area Mobile Weather Unit Internet Access Repeater Safety Zone 	<ul style="list-style-type: none"> Hazard Water Source Restricted Water Source Other Property Pump Water Tank Completed - Inspected In Use - Fire Management Repair Needed No Repair Needed 	<ul style="list-style-type: none"> Other - See Comments Unknown Roto Retardant Drops Fixed Wing Retardant Drops Section Protected Section Private Timberland
---	--	--	--	---	---	---

Suppression Repair

River Complex

CA-KNF-006385

09/23/2021

0 1 2 3 4 5 Miles

1:63,786