



FeatureCategory	RepairStatus	Count
Access or Improved Road	No Repair Needed	36
Access or Improved Road	Repair Needed	20
Access or Improved Road	Unknown	305
Completed Burnout	No Repair Needed	2
Completed Dozer Line	Completed - Inspected	2
Completed Dozer Line	In Progress	2
Completed Dozer Line	No Repair Needed	7
Completed Dozer Line	Repair Needed	133
Completed Dozer Line	Unknown	68
Completed Fuel Break	Unknown	2
Completed Hand Line	No Repair Needed	5
Completed Hand Line	Repair Needed	43
Completed Hand Line	Unknown	63
Completed Mixed Construction Line	No Repair Needed	1
Completed Mixed Construction Line	Repair Needed	2
Completed Mixed Construction Line	Unknown	1
Completed Road as Line	Completed - Inspected	1
Completed Road as Line	No Repair Needed	8
Completed Road as Line	Repair Needed	31
Completed Road as Line	Unknown	58
Confined Line	Unknown	66
Fire Edge	Unknown	91
Planned Dozer Line	Unknown	25
Planned Hand Line	Other - See Comments	1
Planned Hand Line	Unknown	8
Planned Mixed Construction Line	No Repair Needed	1
Planned Mixed Construction Line	Unknown	8
Planned Road as Line	Unknown	14
Repair Line	Repair Needed	1
Retardant Drop	No Repair Needed	4
Retardant Drop	Unknown	2

FeatureCategory	RepairStatus	Count	Length (ft)	Length (mi)
Access or Improved Road	No Repair Needed	36	359296	68.05
Access or Improved Road	Repair Needed	20	175591	33.26
Access or Improved Road	Unknown	305	357409	67.69
Completed Burnout	No Repair Needed	2	10	0.00
Completed Dozer Line	Completed - Inspected	2	2745	0.52
Completed Dozer Line	In Progress	2	5613	1.06
Completed Dozer Line	No Repair Needed	7	10502	1.99
Completed Dozer Line	Repair Needed	133	292631	55.42
Completed Dozer Line	Unknown	68	131596	24.39
Completed Fuel Break	Unknown	2	6498	1.23
Completed Hand Line	No Repair Needed	5	4118	0.78
Completed Hand Line	Repair Needed	43	100282	18.99
Completed Hand Line	Unknown	63	55500	10.51
Completed Mixed Construction Line	No Repair Needed	1	0	0.00
Completed Mixed Construction Line	Repair Needed	2	2973	0.56
Completed Mixed Construction Line	Unknown	1	6165	1.17
Completed Road as Line	Completed - Inspected	1	4110	0.78
Completed Road as Line	No Repair Needed	8	124094	23.5
Completed Road as Line	Repair Needed	31	155683	29.49
Completed Road as Line	Unknown	58	96666	18.69
Confined Line	Unknown	66	1325869	245.81
Fire Edge	Unknown	91	937838	177.62
Planned Dozer Line	Unknown	25	131406	24.89
Planned Hand Line	Other - See Comments	1	6107	1.16
Planned Hand Line	Unknown	8	14416	2.73
Planned Mixed Construction Line	No Repair Needed	1	1487	0.28
Planned Mixed Construction Line	Unknown	8	134382	25.45
Planned Road as Line	Unknown	14	222940	42.22
Repair Line	Repair Needed	1	3151	0.6
Retardant Drop	No Repair Needed	4	2692	0.51
Retardant Drop	Unknown	2	8471	1.6

Fire Edge	Planned Mixed Construction Line	Sling Site	Value at Risk	Repair Point	Hazard	Other - See Comments
Contained Line	Planned Road as Line	Division Break	Other	Landing or Log Deck	Water Source	Unknown
Completed Burnout	Access or Improved Road	Drop Point	Landmark	Restricted Water Source	Roto Retardant Drops	Fixed Wing Retardant Drops
Completed Dozer Line	Repair Line	Closure	Gate	Other Property	Pump	Section Protected
Completed Fuel Break	Retardant Drop	Camp	Bridge	Culvert	Water Tank	Section
Completed Hand Line	Aerial Hazard	Staging Area	Water Development or Drift Site	Clean Up Area	Completed - Inspected	Private Timberland
M - Completed Mixed Construction Line	Check Point	Lookout	Structure Wrap	Mobile Weather Unit	In Use - Fire Management	
R - Completed Road as Line	Hot Spot - Spot Fire	Hot Spot - Spot Fire	Stream Crossing	Internet Access	Repair Needed	
Planned Dozer Line			Road Repair	Repeater	No Repair Needed	
Planned Hand Line			Hellbase	Safety Zone		

Suppression Repair

River Complex CA-KNF-006385 09/24/2021

1:63,786