



Feature/Category	Repair/Status	Count
Access or Improved Road	No Repair Needed	36
Access or Improved Road	Repair Needed	18
Access or Improved Road	Unknown	357,409
Completed Burnout	No Repair Needed	1
Completed Burnout	Completed - Inspected	2
Completed Dozer Line	In Progress	2
Completed Dozer Line	No Repair Needed	37
Completed Dozer Line	Repair Needed	130
Completed Dozer Line	Unknown	88
Completed Fuel Break	Unknown	2
Completed Hand Line	No Repair Needed	4
Completed Hand Line	Repair Needed	43
Completed Hand Line	Unknown	63
Completed Mixed Construction Line	No Repair Needed	1
Completed Mixed Construction Line	Repair Needed	2
Completed Mixed Construction Line	Unknown	1
Completed Road as Line	No Repair Needed	8
Completed Road as Line	Repair Needed	31
Completed Road as Line	Unknown	58
Cracked Line	Unknown	42
Fire Edge	Unknown	97
Planned Dozer Line	Unknown	25
Planned Hand Line	Other - See Comments	1
Planned Hand Line	Unknown	8
Planned Mixed Construction Line	No Repair Needed	1
Planned Mixed Construction Line	Unknown	8
Planned Mixed Construction Line	Unknown	14
Repair Line	Repair Needed	1
Retardant Drop	No Repair Needed	4
Retardant Drop	Unknown	2

Feature/Category	Repair/Status	FREQUENCY	Length (ft)	Length (mi)
Access or Improved Road	No Repair Needed	36	359,296	68.05
Access or Improved Road	Repair Needed	18	175,591	33.26
Access or Improved Road	Unknown	357,409	67,409	12.81
Completed Burnout	No Repair Needed	1	8,469	1.6
Completed Burnout	Completed - Inspected	2	2,745	0.52
Completed Dozer Line	In Progress	2	5,613	1.06
Completed Dozer Line	No Repair Needed	37	10,502	1.99
Completed Dozer Line	Repair Needed	130	292,631	55.42
Completed Dozer Line	Unknown	88	181,596	34.39
Completed Fuel Break	Unknown	2	6,498	1.23
Completed Hand Line	No Repair Needed	4	4,118	0.78
Completed Hand Line	Repair Needed	43	100,392	18.99
Completed Hand Line	Unknown	63	55,500	10.51
Completed Mixed Construction Line	No Repair Needed	1	2,273	0.36
Completed Mixed Construction Line	Repair Needed	2	5,165	1.17
Completed Mixed Construction Line	Unknown	1	124,094	23.5
Completed Road as Line	No Repair Needed	8	155,683	29.49
Completed Road as Line	Repair Needed	31	98,668	18.69
Completed Road as Line	Unknown	58	1,027,780	194.17
Cracked Line	Unknown	42	968,510	183.45
Fire Edge	Unknown	97	131,406	24.89
Planned Dozer Line	Unknown	25	6,107	1.16
Planned Hand Line	Other - See Comments	1	14,416	2.73
Planned Hand Line	Unknown	8	1,467	0.28
Planned Mixed Construction Line	No Repair Needed	1	134,382	25.45
Planned Mixed Construction Line	Unknown	8	222,940	42.22
Planned Mixed Construction Line	Unknown	14	3,151	0.6
Repair Line	Repair Needed	1	2,682	0.51
Retardant Drop	No Repair Needed	4	8,471	1.6
Retardant Drop	Unknown	2		

Fire Edge	Planned Mixed Construction Line	Sling Site	Value at Risk	Repair Point	Hazard	Other - See Comments
Contained Line	Planned Road as Line	Division Break	Other	Landing or Log Deck	Water Source	Unknown
Completed Burnout	Access or Improved Road	Branch Break	Landmark	Restricted Water Source	Roto Retardant Drops	Fixed Wing Retardant Drops
Completed Dozer Line	Repair Line	Drop Point	Gate	Clean Up Area	Culvert	Section Protected
Completed Fuel Break	Retardant Drop	Closure	Bridge	Mobile Weather Unit	Water Tank	Section
Completed Hand Line	Aerial Hazard	Camp	Water Development or Draft Site	Internet Access	Completed - Inspected	Private Timberland
Completed Mixed Construction Line	Check Point	Staging Area	Structure Wrap	Repeater	In Use - Fire Management	
Completed Road as Line	Helispot	Lookout	Stream Crossing	Safety Zone	Repair Needed	
Planned Dozer Line	Hellbase	Hot Spot - Spot Fire	Road Repair		No Repair Needed	
Planned Hand Line			Resource Location			

Suppression Repair

River Complex
CA-KNF-006385
09/25/2021

0 1 2 3 4 5 Miles
1:63,786