



Feature Category	Repair Status	Feature Count
Access	No Repair Needed	1
Access	Repair Needed	1
Access	Other - See Comments	1
Access	Completed	1
Access	In Progress	1
Access	Ready for Inspection	1
Access	Ready for Construction	1
Access	Ready for Use	1
Access	Unknown	1
Access	Value at Risk	1
Access	Other	1
Access	Landmark	1
Access	Gate	1
Access	Bridge	1
Access	Water Development or Draft Site	1
Access	Structure Wrap	1
Access	Stream Crossing	1
Access	Mobile Weather Unit	1
Access	Internet Access	1
Access	Repeater	1
Access	Hazard	1
Access	Water Source	1
Access	Restricted Water Source	1
Access	Other Property	1
Access	Pump	1
Access	Water Tank	1
Access	Completed - Inspected	1
Access	In Progress	1
Access	Repair Needed	1
Access	No Repair Needed	1
Access	Other - See Comments	1
Access	Unknown	1
Access	Section Protracted	1
Access	Section	1
Access	Private Timberland	1

Feature Category	Repair Status	Feature Count	Length (ft)
Access or Improved Road	Completed - Inspection	0	0.0
Access or Improved Road	In Progress	1	0.2
Access or Improved Road	In Use - Fire Management	1	0.2
Access or Improved Road	No Repair Needed	20	120.0
Access or Improved Road	Other - See Comments	0	0.0
Access or Improved Road	Unknown	0	0.0
Access or Improved Road	Value at Risk	0	0.0
Access or Improved Road	Other	0	0.0
Access or Improved Road	Landmark	0	0.0
Access or Improved Road	Gate	0	0.0
Access or Improved Road	Bridge	0	0.0
Access or Improved Road	Water Development or Draft Site	0	0.0
Access or Improved Road	Structure Wrap	0	0.0
Access or Improved Road	Stream Crossing	0	0.0
Access or Improved Road	Mobile Weather Unit	0	0.0
Access or Improved Road	Internet Access	0	0.0
Access or Improved Road	Repeater	0	0.0
Access or Improved Road	Hazard	0	0.0
Access or Improved Road	Water Source	0	0.0
Access or Improved Road	Restricted Water Source	0	0.0
Access or Improved Road	Other Property	0	0.0
Access or Improved Road	Pump	0	0.0
Access or Improved Road	Water Tank	0	0.0
Access or Improved Road	Completed - Inspected	0	0.0
Access or Improved Road	In Progress	0	0.0
Access or Improved Road	Repair Needed	0	0.0
Access or Improved Road	No Repair Needed	0	0.0
Access or Improved Road	Other - See Comments	0	0.0
Access or Improved Road	Unknown	0	0.0
Access or Improved Road	Section Protracted	0	0.0
Access or Improved Road	Section	0	0.0
Access or Improved Road	Private Timberland	0	0.0

- Completed - Inspected
 - In Progress
 - Repair Needed
 - No Repair Needed
 - Other - See Comments
 - Unknown
 - Section Protracted
 - Section
 - Private Timberland
- Completed Burnout
 - Completed Dozer Line
 - Completed Fuel Break
 - Completed Hand Line
 - Completed Mixed Construction Line
 - Completed Plow Line
 - Completed Road as Line
 - Planned Dozer Line
 - Planned Hand Line
- Hot Spot - Spot Fire
 - Value at Risk
 - Other
 - Landmark
 - Gate
 - Bridge
 - Water Development or Draft Site
 - Structure Wrap
 - Stream Crossing
- Road Repair
 - Resource Location
 - Repair Point
 - Landing or Log Deck
 - Hazard Tree
 - Dozer Unit
 - Culvert
 - Clean Up Area
 - Mobile Weather Unit
- Internet Access
 - Repeater
 - Hazard
 - Water Source
 - Restricted Water Source
 - Other Property
 - Pump
 - Water Tank
- Helibase
 - Sling Site
 - Division Break
 - Drop Point
 - Closure
 - Staging Area
 - Lookout

Suppression Repair
 River Complex
 CA-KNF-006385
 10/11/2021 07:00

0 1 2 3 4 5 Miles
1:63,786