



Feature Category	Repair Status	Feature Count
Access or Improved Road	Completed - Inspected	8
Access or Improved Road	In Progress	2
Access or Improved Road	Repair Needed	3
Access or Improved Road	No Repair Needed	203
Access or Improved Road	Other - See Comments	1
Access or Improved Road	Unknown	39
Completed Dozer Line	Completed - Inspected	193
Completed Dozer Line	Completed - Ready for Inspection	8
Completed Dozer Line	In Progress	45
Completed Dozer Line	No Repair Needed	5
Completed Dozer Line	Other - See Comments	2
Completed Dozer Line	Repair Needed	4
Completed Dozer Line	Unknown	8
Completed Fuel Break	Completed - Inspected	3
Completed Fuel Break	No Repair Needed	2
Completed Hand Line	Completed - Inspected	67
Completed Hand Line	Completed - Ready for Inspection	9
Completed Hand Line	In Progress	4
Completed Hand Line	No Repair Needed	56
Completed Hand Line	Repair Needed	53
Completed Hand Line	Unknown	10
Completed Hand Construction Line	Completed - Inspected	10
Completed Hand Construction Line	In Progress	2
Completed Hand Construction Line	No Repair Needed	1
Completed Hand Construction Line	Other - See Comments	2
Completed Hand Construction Line	Repair Needed	2
Completed Hand Construction Line	Unknown	11
Completed Phone Line	Completed - Inspected	46
Completed Road as Line	Completed - Inspected	48
Completed Road as Line	No Repair Needed	2
Completed Road as Line	Other - See Comments	31
Completed Road as Line	Repair Needed	31
Completed Road as Line	Unknown	2
Completed Road as Line	No Repair Needed	113
Fire Edge	Completed - Inspected	115
Planned Dozer Line	No Repair Needed	15
Planned Hand Line	No Repair Needed	11
Planned Hand Construction Line	No Repair Needed	5
Planned Road as Line	No Repair Needed	10
Repair Unit	Completed - Inspected	1
Retardant Drop	Completed - Inspected	1
Retardant Drop	No Repair Needed	7

Feature Category	Repair Status	Feature Count	Length (ft)
Access or Improved Road	Completed - Inspected	8	25.1
Access or Improved Road	In Progress	2	3.7
Access or Improved Road	Repair Needed	3	3.7
Access or Improved Road	No Repair Needed	203	141.1
Access or Improved Road	Other - See Comments	1	0.1
Access or Improved Road	Unknown	39	1.6
Completed Dozer Line	Completed - Inspected	193	191.8
Completed Dozer Line	Completed - Ready for Inspection	8	3.6
Completed Dozer Line	In Progress	45	104.4
Completed Dozer Line	No Repair Needed	5	1.5
Completed Dozer Line	Other - See Comments	2	0.8
Completed Dozer Line	Repair Needed	4	1.5
Completed Dozer Line	Unknown	8	12.2
Completed Fuel Break	Completed - Inspected	3	3
Completed Fuel Break	No Repair Needed	2	1.5
Completed Hand Line	Completed - Inspected	67	166.2
Completed Hand Line	Completed - Ready for Inspection	9	9
Completed Hand Line	In Progress	4	16.4
Completed Hand Line	No Repair Needed	56	107.7
Completed Hand Line	Repair Needed	53	131.4
Completed Hand Line	Unknown	10	16.8
Completed Hand Construction Line	Completed - Inspected	10	10
Completed Hand Construction Line	In Progress	2	1.6
Completed Hand Construction Line	No Repair Needed	1	0.2
Completed Hand Construction Line	Other - See Comments	2	1.6
Completed Hand Construction Line	Repair Needed	2	1.6
Completed Hand Construction Line	Unknown	11	17.9
Completed Phone Line	Completed - Inspected	46	101.3
Completed Road as Line	Completed - Inspected	48	101.3
Completed Road as Line	No Repair Needed	2	1.6
Completed Road as Line	Other - See Comments	31	118.3
Completed Road as Line	Repair Needed	31	118.3
Completed Road as Line	Unknown	2	1.6
Completed Road as Line	No Repair Needed	113	444.5
Fire Edge	Completed - Inspected	115	394.4
Planned Dozer Line	No Repair Needed	15	15
Planned Hand Line	No Repair Needed	11	11
Planned Hand Construction Line	No Repair Needed	5	16.8
Planned Road as Line	No Repair Needed	10	10
Repair Unit	Completed - Inspected	1	0.1
Retardant Drop	Completed - Inspected	1	0.1
Retardant Drop	No Repair Needed	7	17.7

Suppression Repair
River Complex
CA-KNF-006385
10/14/2021 07:00

0 1 Miles
1:20,000

— Completed - Inspected	— Completed Dozer Line		Other
— In Progress	— Completed Hand Line		Bridge
● Repair Needed	— Retardant Drop		Water Development or Draft Site
— No Repair Needed	— Planned Dozer Line		Stream Crossing
— Unknown	— Planned Hand Line		Road Repair
— Contained Line	— Planned Road as Line		
— Completed Burnout			

	Resource Location		Water Source
	Repair Point		Completed - Inspected
	Dozer Push		Repair Needed
	Mobile Weather Unit		No Repair Needed
	Repeater		Unknown
	Hazard		Section Protracted
			Section