



Feature Category	Repair Status	Feature Count/Length (ft)
Access or Improved Road	Completed - Inspected	8 20.1
Access or Improved Road	In Progress	1 0.3
Access or Improved Road	Ready for Inspection	3 0.7
Access or Improved Road	Fire Repair Needed	2 0.5
Access or Improved Road	Other - See Comments	3 8.1
Access or Improved Road	Unknown	2 5.1
Access or Improved Road	Unknown	39 10.6
Completed Dozer Line	No Repair Needed	131 18.8
Completed Dozer Line	Completed - Inspected	8 1.9
Completed Dozer Line	Ready for Inspection	2 0.5
Completed Dozer Line	In Use - Fire Management	5 1.3
Completed Dozer Line	Fire Repair Needed	45 12.8
Completed Dozer Line	Other - See Comments	2 0.5
Completed Dozer Line	Unknown	4 10.3
Completed Dozer Line	Unknown	8 11.2
Completed Fuel Break	Completed - Inspected	3 0.1
Completed Fuel Break	No Repair Needed	2 0.5
Completed Hand Line	Completed - Inspected	67 18.2
Completed Hand Line	Ready for Inspection	2 0.7
Completed Hand Line	In Use - Fire Management	4 0.4
Completed Hand Line	No Repair Needed	1 0.1
Completed Hand Line	In Use - Fire Management	56 10.7
Completed Hand Line	Repair Needed	5 0.3
Completed Hand Line	Unknown	2 0.3
Completed Hand Construction Line	Completed - Inspected	10 0.8
Completed Hand Construction Line	In Progress	2 0.1
Completed Hand Construction Line	In Use - Fire Management	1 0.2
Completed Hand Construction Line	Fire Repair Needed	2 0.1
Completed Hand Construction Line	Other - See Comments	2 0.8
Completed Hand Construction Line	Unknown	1 0.1
Completed Hand Construction Line	Unknown	1 0.1
Completed Hand Line	Completed - Inspected	11 0.3
Completed Road as Line	Completed - Inspected	46 101.1
Completed Road as Line	In Progress	1 0.1
Completed Road as Line	No Repair Needed	48 14.4
Completed Road as Line	Other - See Comments	2 0.1
Completed Road as Line	Repair Needed	3 0.1
Completed Road as Line	Unknown	2 0.1
Completed Road as Line	Unknown	113 444.5
Fire Edge	No Repair Needed	115 39.4
Planned Dozer Line	No Repair Needed	15 0.1
Planned Fuel Break	No Repair Needed	1 0.1
Planned Hand Construction Line	No Repair Needed	5 0.1
Planned Road as Line	No Repair Needed	10 29.8
Repair Line	Completed - Inspected	1 0.1
Retardant Drop	Completed - Inspected	1 0.1
Retardant Drop	No Repair Needed	7 0.1

Feature Category	Repair Status	Feature Count/Length (ft)
Access or Improved Road	Completed - Inspected	8 20.1
Access or Improved Road	In Progress	1 0.3
Access or Improved Road	Ready for Inspection	3 0.7
Access or Improved Road	Fire Repair Needed	2 0.5
Access or Improved Road	Other - See Comments	3 8.1
Access or Improved Road	Unknown	2 5.1
Access or Improved Road	Unknown	39 10.6
Completed Dozer Line	No Repair Needed	131 18.8
Completed Dozer Line	Completed - Inspected	8 1.9
Completed Dozer Line	Ready for Inspection	2 0.5
Completed Dozer Line	In Use - Fire Management	5 1.3
Completed Dozer Line	Fire Repair Needed	45 12.8
Completed Dozer Line	Other - See Comments	2 0.5
Completed Dozer Line	Unknown	4 10.3
Completed Dozer Line	Unknown	8 11.2
Completed Fuel Break	Completed - Inspected	3 0.1
Completed Fuel Break	No Repair Needed	2 0.5
Completed Hand Line	Completed - Inspected	67 18.2
Completed Hand Line	Ready for Inspection	2 0.7
Completed Hand Line	In Use - Fire Management	4 0.4
Completed Hand Line	No Repair Needed	1 0.1
Completed Hand Line	In Use - Fire Management	56 10.7
Completed Hand Line	Repair Needed	5 0.3
Completed Hand Line	Unknown	2 0.3
Completed Hand Construction Line	Completed - Inspected	10 0.8
Completed Hand Construction Line	In Progress	2 0.1
Completed Hand Construction Line	In Use - Fire Management	1 0.2
Completed Hand Construction Line	Fire Repair Needed	2 0.1
Completed Hand Construction Line	Other - See Comments	2 0.8
Completed Hand Construction Line	Unknown	1 0.1
Completed Hand Line	Completed - Inspected	11 0.3
Completed Road as Line	Completed - Inspected	46 101.1
Completed Road as Line	In Progress	1 0.1
Completed Road as Line	No Repair Needed	48 14.4
Completed Road as Line	Other - See Comments	2 0.1
Completed Road as Line	Repair Needed	3 0.1
Completed Road as Line	Unknown	2 0.1
Completed Road as Line	Unknown	113 444.5
Fire Edge	No Repair Needed	115 39.4
Planned Dozer Line	No Repair Needed	15 0.1
Planned Fuel Break	No Repair Needed	1 0.1
Planned Hand Construction Line	No Repair Needed	5 0.1
Planned Road as Line	No Repair Needed	10 29.8
Repair Line	Completed - Inspected	1 0.1
Retardant Drop	Completed - Inspected	1 0.1
Retardant Drop	No Repair Needed	7 0.1

Completed - Inspected	Contained Line	Planned Hand Line	Sling Site	Value at Risk	Road Repair	Internet Access	Completed - Inspected
In Use - Fire Management	Completed Dozer Line	Planned Road as Line	Division Break	Other	Resource Location	Repeater	In Progress
Completed - Ready for Inspection	Completed Fuel Break	Access or Improved Road	Drop Point	Landmark	Repair Point	Hazard	Repair Needed
In Progress	Completed Hand Line	Retardant Drop	Water	Hazard Tree	Water Source	No Repair Needed	Other - See Comments
Repair Needed	Completed Mixed Construction Line	Aerial Hazard	Restricted Water Source	Dozer Push	Other Property	Unknown	Section Protracted
No Repair Needed	Completed Plow Line	Check Point	Pump	Clean Up Area	Draft Site	Section	Private Timberland
Other - See Comments	Completed Road as Line	Helispot	Water Tank	Mobile Weather Unit	Structure Wrap		
Unknown	Planned Dozer Line	Helibase			Stream Crossing		

Suppression Repair  
 River Complex  
 CA-KNF-006385  
 10/14/2021 07:00

1:40,000