



Feature Category	Repair Status	Features Count (Length (MI))
Access or Improved Road	Completed	2
Access or Improved Road	In Progress	2
Access or Improved Road	No Repair Needed	355 (142)
Access or Improved Road	Other - See Comments	4
Access or Improved Road	Repair Needed	8
Completed Burnout	No Repair Needed	18
Completed Dozer Line	Completed - Inspected	228
Completed Dozer Line	In Progress	1
Completed Dozer Line	No Repair Needed	28
Completed Dozer Line	Other - See Comments	1
Completed Dozer Line	Repair Needed	41
Completed Dozer Line	Unknown	4
Completed Dozer Line	Value at Risk	75
Completed Fuel Break	Completed - Inspected	1
Completed Fuel Break	No Repair Needed	2
Completed Fuel Break	Repair Needed	22
Completed Hand Line	Completed - Ready for Inspection	9
Completed Hand Line	In Progress	1
Completed Hand Line	No Repair Needed	4
Completed Hand Line	Other - See Comments	1
Completed Hand Line	Repair Needed	48
Completed Hand Line	Unknown	13
Completed Hand Line	Value at Risk	2
Completed Hand Construction Line	In Progress	2
Completed Hand Construction Line	No Repair Needed	7
Completed Hand Construction Line	Other - See Comments	1
Completed Hand Construction Line	Repair Needed	10
Completed Hand Construction Line	Unknown	1
Completed Hand Construction Line	Value at Risk	15
Completed Road as Line	Completed - Inspected	53
Completed Road as Line	No Repair Needed	49
Completed Road as Line	Other - See Comments	1
Completed Road as Line	Repair Needed	11
Completed Road as Line	Value at Risk	13
Completed Road as Line	Unknown	113
Completed Road as Line	Value at Risk	115
Completed Road as Line	Value at Risk	16
Planned Hand Line	No Repair Needed	11
Planned Hand Line	Repair Needed	13
Planned Hand Line	Unknown	15
Planned Hand Line	Value at Risk	1
Planned Hand Line	Value at Risk	1
Planned Hand Line	Value at Risk	7
Planned Hand Line	Value at Risk	12

Suppression Repair
River Complex
CA-KNF-006385
10/15/2021 07:00

<ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown Fire Edge Contained Line 	<ul style="list-style-type: none"> Completed Burnout Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Hand Construction Line Completed Hand Construction Line Completed Hand Construction Line Completed Hand Construction Line Completed Hand Construction Line Completed Hand Construction Line Completed Road as Line Completed Road as Line Completed Road as Line Completed Road as Line Completed Road as Line Planned Mixed Construction Line Planned Road as Line Repair Line Retardant Drop Aerial Hazard Check Point Planned Dozer Line Planned Hand Line 	<ul style="list-style-type: none"> Value at Risk Landmark Gate Bridge Water Development or Draft Site Structure Wrap Stream Crossing Road Repair 	<ul style="list-style-type: none"> Repeater Hazard Water Source Restricted Water Source Other Property Pump Water Tank Completed - Inspected In Progress 	<ul style="list-style-type: none"> Repair Needed No Repair Needed Other - See Comments Unknown Section Protected Section Private Timberland Forest Service
---	---	--	---	--

1:63,786