

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Repair Needed	1	Div A and W		crosses 1 drainage
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	2	Div A and W	Delete portions that overlay road as line entry	West side of line #2
MCFARLAND	Completed Dozer Line	Repair Needed	2	Div A and W	Delete portions that overlay road as line entry	East side of line #2
MCFARLAND	Completed Dozer Line	Repair Needed	3	Div A and W		Tactical ridgetop repair needed. Likely old line from telephone fire. May be primary ridge to keep open and only repair with drainage.
MCFARLAND	Completed Hand Line	Repair Needed	4	Div A and W	Arch MJP assessed	
MCFARLAND	Completed Dozer Line	Repair Needed	5	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	6	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	7	Div A and W		Tactical ridgetop repair needed
MCFARLAND	Completed Dozer Line	Repair Needed	8	Div S		Tactical ridgetop repair needed
MCFARLAND	Completed Dozer Line	Repair Needed	9	Div S		
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	10	Div A and W		Tactical ridgetop repair needed
MCFARLAND	Completed Dozer Line	Repair Needed	11	Div E and Contingency	1 blade, berms 1-3 feet	
MCFARLAND	Completed Dozer Line	Repair Needed	12	Div A and W	1-2 blades wide, berms 1-4 feet. Fuels accumulation on downslope side of line	Berms need knocked down/ tank trapped
MCFARLAND	Completed Hand Line	Repair Needed	13	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	14	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	15	Div S		
MCFARLAND	Completed Dozer Line	Repair Needed	16	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	17	Div A and W		
MCFARLAND	Completed Hand Line	Repair Needed	18	Div A and W	Around a dispersed camp site (hunting camp)	Low priority repair and just where it meets the creek
MCFARLAND	Completed Dozer Line	Repair Needed	19	Div A and W	Please delete this line and use the more accurate overlaid pieces. This line is not accurate and doesn't exist along road. TS 8/17	
MCFARLAND	Completed Dozer Line	Repair Needed	20	Div S		Tactical ridgetop repair needed
MCFARLAND	Completed Road as Line	Repair Needed	21	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	22	Div A and W	Black on both sides. 3 blades wide. Non-tactical.	
MCFARLAND	Completed Dozer Line	Repair Needed	23	Div A and W	Mostly 3 blades wide. Parts are very steep. Excavator	

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Repair Needed	24	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	25	Div A and W		Tactical ridgetop repair needed. Bladed 1-3 blades wide. Some fuel scatter on sides, old road was opened up for use
MCFARLAND	Completed Dozer Line	Repair Needed	26	Div A and W		Berms 1-4 ft High, fuel accumulation on sides. Dozer path 2-3 blades wide
MCFARLAND	Completed Dozer Line	Repair Needed	27	Div A and W		Dozer line, 1-2 blades wide. Stops near contour line. READ D. Plummer 08/10
MCFARLAND	Completed Dozer Line	Repair Needed	28	Div A and W	1-5 blades wide. Significant side throw fuels accumulations. Berms 1-4 ft. Water bars required in	Tactical ridgetop repair needed
MCFARLAND	Completed Mixed Construction Line	Repair Needed	29	Div A and W	Road adjacent 1-5 blades wide. Significant fuels accumulation, berms 1-4 ft.	
MCFARLAND	Completed Dozer Line	Repair Needed	30	Div A and W	1-2 blades wide, berms 1-2 feet. Moderate fuels	
MCFARLAND	Completed Dozer Line	Repair Needed	31	Div A and W	1-2 blades wide, berms 1-3 feet, moderate fuels accumulation	
MCFARLAND	Completed Dozer Line	Repair Needed	32	Div A and W	1 blade, berms 1-2 feet. Needs water bars	
MCFARLAND	Completed Dozer Line	Repair Needed	33	Div A and W	1 blade, berms 1-3 ft. Needs waterbars	
MCFARLAND	Completed Dozer Line	Repair Needed	34	Div A and W	1-2 blades, berms 1-3 feet. Passes through drainage	
MCFARLAND	Completed Dozer Line	Repair Needed	35	Div A and W	1-2 blades wide, berms 1-2 feet. Moderate fuels accumulation	
MCFARLAND	Completed Dozer Line	Repair Needed	36	Div A and W	1-2 blades wide, berms 1-3 feet, moderate fuels	
MCFARLAND	Completed Dozer Line	Repair Needed	37	Div A and W	Unmapped dozer line on private property. Potentially put	
MCFARLAND	Completed Hand Line	Repair Needed	38	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	39	Div A and W	Not precise but reflects general location and extent of	Tactical ridgetop repair needed
MCFARLAND	Completed Dozer Line	Repair Needed	40	Div A and W		Dozer line not exact, road adjacent. berms 12-24 inches high. 1-2 blades wide
MCFARLAND	Completed Dozer Line	Repair Needed	41	Div A and W	3 blades wide. Berms to 3 feet. Fuels accumulation	Excavator. Needs water bars, berms pulled back and veg scattered
MCFARLAND	Completed Dozer Line	Repair Needed	42	Div A and W	1-4 blades, berms to 4 feet but mostly 1. Fuels accumulations mostly 12" trees. Crosses dry creek bed	Excavator. Berms need pulled back and veg scattered. Needs water bars; could use downed trees on site.
MCFARLAND	Completed Dozer Line	Repair Needed	43	Div A and W	Primarily 1 blade, berms 1-2 feet. Needs erosion control	Excavator. Water bars or horizontally placed trees
MCFARLAND	Road Repair	Repair Needed	44	Div A and W	Berms 1-2 feet need knocked down. Roads need graded	
MCFARLAND	Completed Dozer Line	Repair Needed	45	Div A and W	1 blade, berms 1-2 feet.	Needs erosion control features, berms pulled back
MCFARLAND	Road Repair	Repair Needed	46	Div A and W	6-12" berm needs knocked down and road graded	
MCFARLAND	Completed Dozer Line	Repair Needed	47	Div A and W	Dozer line 1-3 blades wide, some fuels accumulation. READ D. Plummer 08/11	
MCFARLAND	Completed Dozer Line	Repair Needed	48	Div A and W	Dozer line downslope, 1-3 blades wide. READ D. Plummer 08/11	
MCFARLAND	Completed Dozer Line	Repair Needed	49	Div A and W	Dozer line 1-3 blades wide. Some fuels accumulation on side pushes.	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	50	Div A and W	Short dozer push off the main road, 1-2 blades wide	

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Repair Needed	51	Div A and W	Dozer line 1-3 blades wide, wider in some spots with debris pushed out of the path.	
MCFARLAND	Completed Dozer Line	Repair Needed	52	Div A and W	Dozer line 1-3 blades wide	
MCFARLAND	Road Repair	Repair Needed	53	Div A and W	29N25 Road graded	Dirt berm along downhill side of road from hwy 36 to DP4. Dozer
MCFARLAND	Repair Line	Repair Needed	54	Div A and W	Old road to comms station. Dozed through. Keep open as	1 blade wide, several pushes along road. Need berms removed and
MCFARLAND	Road Repair	Repair Needed	55	Div A and W	Repair as road? Or is it decommissioned? Leave open for future use?	Dirt firms on both sides of the road, several large vegetation piles and 12 inch diameter trees a long road side.
MCFARLAND	Completed Dozer Line	Repair Needed	56	Div A and W		Single blade; steep, needs drainage- connects two roads on curve
MCFARLAND	Completed Dozer Line	Repair Needed	57	Div A and W		Standard repair, narrow, one blade wide
MCFARLAND	Completed Dozer Line	Repair Needed	58	Div A and W		Standard repair, narrow at bottom and wide at top of hill near
MCFARLAND	Completed Dozer Line	Repair Needed	59	Div A and W	Extremely steep up from DP1 to ridge top. ~One blade wide. Crosses riparian area/streams at 28rd/hwy36 turn off. UNAUTHORIZED route- needs earthen barrier, water bars, and berms pulled back (TFelbeck)	Tactical ridgetop repair needed. Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	60	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	61	Div A and W	New Dozerline. Not along road on this segment. varies 1-5 blades wide. Medium size trees pushed at north end of	
MCFARLAND	Completed Dozer Line	Repair Needed	62	Div A and W	Old closed road reopened for Dozerline and access. Needs repaired, closed. 081121.	
MCFARLAND	Completed Dozer Line	Repair Needed	63	Div A and W	Dozerline along OHV road. Two blades wide. 081121	
MCFARLAND	Completed Dozer Line	Repair Needed	64	Div A and W	Parallels and veers from keep trail. Mostly 3-4 blades wide. Black on both sides. Unauthorized rat needs closed	
MCFARLAND	Completed Dozer Line	Repair Needed	65	Div A and W	Dozerline parallels road and has eyebrows. 2-3 blades	
MCFARLAND	Completed Dozer Line	Repair Needed	66	Div A and W	2-3 blades wide Dozerline. On ridge. 081121	
MCFARLAND	Completed Dozer Line	Repair Needed	67	Div A and W	Reopened logging road and off road. Single blade. Repair/close. 081121.	
MCFARLAND	Road Repair	Repair Needed	68	Div A and W	Road as line. Outsloped road cut. Need berm cut down to prevent rilling. 081121	
MCFARLAND	Road Repair	Repair Needed	69	Div A and W	Dozer improved road. No repair needed. 081121	
MCFARLAND	Completed Dozer Line	Repair Needed	70	Div A and W	Dozer line 1-3 blades wide, lots of fuels pushed aside and	Excavator recommended
MCFARLAND	Completed Dozer Line	Repair Needed	71	Div A and W	Dozer line 1-3 blades wide. Connects to dozer push and road crossing. Soft soil and dense vegetation berms. TS	
MCFARLAND	Completed Dozer Line	Repair Needed	72	Div A and W	Old dozer line, 1-3 blades wide and push a few hundred	Excavator recommended
MCFARLAND	Completed Dozer Line	Repair Needed	73	Div A and W	Loops into line to the West. 1-3 blades wide. REAF D. Plummer 08/12	Excavator recommended
MCFARLAND	Completed Dozer Line	Repair Needed	74	Div A and W	Dozer line 2-4 blades wide, lots of material movement (slash and dirt). REAF D. Plummer 08/12	Excavator, possibly dozer to move the dirt back to original location.
MCFARLAND	Completed Road as Line	Repair Needed	75	Div S	1-2 ft berms. Needs graded and berms knocked down/ erosion control features	
MCFARLAND	Completed Dozer Line	Repair Needed	77	Div A and W	1-2 blades wide, berms to 3 feet. Needs water bars,	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	78	Div A and W	1-2 blades, berms to 3 feet. Significant fuels accumulation	Excavator

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Repair Needed	80	Div A and W	Short dozer push along the end of the road. 1-3 foot High berms, some fuels accumulation. READ D. Plummer	
MCFARLAND	Completed Dozer Line	Repair Needed	81	Div A and W	Dozer line, one follows the road. 1-2 blades wide, very steep. READ D. Plummer 08/13	
MCFARLAND	Completed Dozer Line	Repair Needed	82	Div A and W	Nearly level Dozerline. Single blade wide. Small berm.	Just close. Sensitive soils.
MCFARLAND	Completed Dozer Line	Repair Needed	83	Div A and W	Mostly 1 blade. Berms to 4 ft. Berms need pulled back. Needs water bars	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	84	Div A and W	1 blade, minimal berms. needs berms pulled back and water bars. Tfelbeck	Hand crew or excavator
MCFARLAND	Completed Dozer Line	Repair Needed	85	Div A and W	1 blade, 1 feet berms. Need pulled back and concealed w	Hand crew or excavator
MCFARLAND	Completed Dozer Line	Repair Needed	86	Div A and W	1-5 blades wide. Berms to 4 feet. Significant fuels accumulation. Needs berms pulled back and water bars constructed (tfelbeck)	Excavator
MCFARLAND	Completed Road as Line	Repair Needed	87	Div A and W	1-2 feet berm on outboard side of road needs drainage punched in. Tfelbeck	
MCFARLAND	Completed Dozer Line	Repair Needed	88	Div A and W	2 blades, berms to 4 feet. Fuels accumulations. Needs	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	89	Div A and W	1-4 blades, berms to 4 feet; very rocky. Fuels accumulation. Needs berms pulled back	
MCFARLAND	Completed Dozer Line	Repair Needed	90	Div A and W	1 blade, berms to 3 feet. Needs water bars and berms pulled back (tfelbeck)	
MCFARLAND	Completed Road as Line	Repair Needed	91	Div A and W	Mostly 1 blade, berms to three feet. Needs berms pulled	Tactical ridgetop repair needed. Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	92	Div A and W	1 blade, berms to 4 feet. Needs berms pulled back and water bars (tfelbeck)	
MCFARLAND	Completed Dozer Line	Repair Needed	93	Div A and W	1-3 blades, berms to 3 feet. Crosses drainage. Needs berms pulled back and water bars. Drainage needs contouring	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	94	Div A and W	Mostly 1 blade, berms 1-3 ft. Needs berms pulled back (tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	95	Div A and W	1 blade, berms to 3 feet. Needs berms pulled back and water bars. Low gps accuracy- starts downslope of road	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	96	Div A and W		Single blade line connects staging area to lines above. Meets a 5 blade wide dozed area on top of first bench. Will drain directly into
MCFARLAND	Completed Dozer Line	Repair Needed	97	Div A and W		Single blade connects staging area to hwy36
MCFARLAND	Completed Dozer Line	Repair Needed	98	Div A and W		Tactical ridgetop repair needed. 5 blades wide on top of ridge, heavy berms. Standard repair.
MCFARLAND	Completed Dozer Line	Repair Needed	99	Div A and W		This section pushed up serpentine soils. Do not water bar in any rocky areas, only soft soil.
MCFARLAND	Completed Dozer Line	Repair Needed	100	Div A and W		Very steep. High priority for drainage repair. 2-4 blades wide.

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Repair Needed	101	Div A and W		Can be repaired, extra line from dozer entry/exit
MCFARLAND	Completed Dozer Line	Repair Needed	102	Div A and W		Tactical ridgetop repair needed. Dozer line along roadside, as one line. Grade road, pull back berms and vegetation from edge of dozer
MCFARLAND	Road Repair	Repair Needed	103	Div A and W		Grade, water, and knock down small dirt berms
MCFARLAND	Road Repair	Repair Needed	104	Div A and W		Narrow, some fuels built up in berms.
MCFARLAND	Road Repair	Repair Needed	105	Div A and W		Grade, water, and knock down small dirt berms
MCFARLAND	Road Repair	Repair Needed	106	Div A and W		Grade, water, and knock down small dirt berms
MCFARLAND	Completed Dozer Line	Repair Needed	107	Div A and W	1-4 blades wide, some parts outward push, main section has been driven on as if it was a road, some fuels pushed	Tactical ridgetop repair needed
MCFARLAND	Completed Road as Line	Repair Needed	108	Div A and W	1-2 blades wide next to road, some push, most fuels consumed by fire.	
MCFARLAND	Completed Hand Line	No Repair Needed	109	Div A and W	Hand line around spot fire	No repair needed, rocky soils, small area, no threat to cause damage if left as is
MCFARLAND	Completed Dozer Line	Repair Needed	110	Div A and W	1 blade next OHV trail, diverts from trail by large rock, heavy fuels on fire side, reopened line from august	
MCFARLAND	Completed Dozer Line	Repair Needed	111	Div A and W	1-2 blades possibly along ohv trail. Reopened from august	
MCFARLAND	Completed Dozer Line	Repair Needed	112	Div A and W		Likely old line from telephone fire. May be primary ridge to keep open and only repair with drainage. Crosses telephone ridge road several times.
MCFARLAND	Completed Dozer Line	Repair Needed	113	Div A and W		Tactical ridgetop repair needed. Likely old line from telephone fire. May be primary ridge to keep open and only repair with drainage.
MCFARLAND	Completed Dozer Line	Repair Needed	114	Div A and W		Likely old line from telephone fire. May be primary ridge to keep open and only repair with drainage. Crosses telephone ridge road several times.
MCFARLAND	Completed Dozer Line	Repair Needed	115	Div S		
MCFARLAND	Completed Road as Line	Repair Needed	116	Div A and W	Not dozer line.	
MCFARLAND	Completed Dozer Line	Repair Needed	117	Div A and W		Standard repair 2-3 blades wide. Heavy fuels in berm. Excavator needed, or saws crew and dozer
MCFARLAND	Completed Dozer Line	Repair Needed	118	Div A and W		Standard repair TS 8/14 single blade , dead end
MCFARLAND	Road Repair	Repair Needed	119	Div A and W		Knock down berm as needed to allow drainage
MCFARLAND	Completed Dozer Line	Repair Needed	120	Div A and W	Dozer put along road 83, 1 blade wide. Some berms (1-3	Excavator work for steep grade, wider blade width on northern
MCFARLAND	Completed Dozer Line	Repair Needed	121	Div A and W	Dozer line 1-4 (mostly more than 1) blades wide. VERY steep, lots of fuel accumulation and a few dozer pushes off the side. Ties into ridge dozer line. Lots of dirt moved	Significant repair with an excavator will be needed, lots of fuels and dirt movement and usually several blades wide.
MCFARLAND	Completed Dozer Line	Repair Needed	122	Div A and W	Dozer line to slight east of main line, leaves a center	Will need excavator for steep grade and significant fuels
MCFARLAND	Completed Dozer Line	Repair Needed	123	Div A and W	Dozer line up to McFarland ridge. Steep in the first	Excavator needed for width of repair area and steep grade.
MCFARLAND	Completed Dozer Line	Repair Needed	124	Div A and W	Dozer track coming down from McFarland ridge that	
MCFARLAND	Completed Dozer Line	Repair Needed	125	Div A and W	Mostly 1 blade, 1-3 ft berms. Needs berms pulled back	Excavator

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Completed - Ready for In	126	Div A and W	1-2 bodes, berms mostly 2 feet. Needs berms pulled in and water-barred. Needs barriers where connects to road (tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	127	Div A and W	Mostly 2 blades wide. Berms to 4 feet. Some fuels accumulation. Needs berms pulled back, water bars, and	Excavator
MCFARLAND	Completed Dozer Line	Completed - Inspected	128	Div A and W	2-6 blades wide. Berms to 4 feet. Berms need pulled back and needs earthen barriers where meets road. (Tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Completed - Inspected	129	Div A and W	1-5 blades wide. Several large pushes along top of ridge. Berms 2-4 feet. Need pulled back. Needs earthen barriers	Excavator
MCFARLAND	Completed Dozer Line	Completed - Inspected	130	Div A and W	1-3 blades wide. Pushes throughout. Berms to 4 feet. Needs berms pulled back and earthen barriers where meets road (tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Completed - Inspected	131	Div A and W	1-4 blades. Berms to 2 feet. Needs berms pulled in, veg scattered throughout (tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	132	Div S		Tactical ridgetop repair needed
MCFARLAND	Completed Dozer Line	Repair Needed	133	Div S		
MCFARLAND	Completed Dozer Line	Repair Needed	134	Div S		
MCFARLAND	Completed Hand Line	Repair Needed	135	Div S		
MCFARLAND	Completed Road as Line	Repair Needed	136	Div A and W	Shows being actual road on Ops Repair map and forest	Needs berms pulled, brush chipped, and bring back dozer pushes
MCFARLAND	Completed Road as Line	Repair Needed	137	Div A and W	Shows being actual road on Ops Repair map and forest map. REAF Klotz	Pull berms and chip slash on side of road
MCFARLAND	Completed Dozer Line	Repair Needed	138	Div A and W		Steep, needs water bars, pull berms and scatter fuels. REAF Klotz
MCFARLAND	Completed Road as Line	Repair Needed	139	Div A and W	Shows being actual road on Ops Repair map and forest map. REAF Klotz	Pull berms, chip brush
MCFARLAND	Completed Dozer Line	Repair Needed	140	Div A and W	Side dozer push about 200ft in length	Block access at main road, pull some slash. REAF Klotz
MCFARLAND	Completed Road as Line	Repair Needed	141	Div A and W	Shows being actual road on Ops Repair map and forest map. REAF Klotz	Chip brush, pull berms.
MCFARLAND	Completed Road as Line	Repair Needed	142	Div A and W	Follows unauthorized trail. 2 blades, berms to 2 feet. Very rocky. Needs berms pulled in and earthen barrier to prevent use (tfelbeck)	Excavator
MCFARLAND	Completed Road as Line	Completed - Inspected	143	Div A and W	Mostly 1 blade, to 6 in places, with occasional push. Berms to 4 feet need knocked down. Needs recontoured, berms knocked down, and barriers constructed where	Excavator

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Mixed Construction Line	Completed - Inspected	144	Div A and W	Berms to 3 feet. Occasional push. Need berms pulled back and fuels scattered (tfelbeck)	Excavator
MCFARLAND	Completed Road as Line	Completed - Inspected	145	Div A and W	1 blade, berms to 3 ft. Knees berms knocked down, watered, and graded (tfelbeck)	Excavator, graded
MCFARLAND	Road Repair	Repair Needed	146	Div A and W	18" berm on outboard side of line needs knocked down	
MCFARLAND	Road Repair	Repair Needed	147	Div A and W	1-2' berm needs knocked down for drainage	
MCFARLAND	Completed Dozer Line	Repair Needed	148	Div A and W	Mostly one blade. Berms to 2 feet. Needs berms pulled in	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	149	Div A and W	Mostly one blade, 1ft berms. Needs water bars and berms pulled in	
MCFARLAND	Completed Dozer Line	Repair Needed	150	Div A and W	1 blade, berms to two feet. Needs berms pulled back, water bars	Excavator
MCFARLAND	Completed Hand Line	Repair Needed	151	Div A and W	Heads straight downhill; erosion concern	Hand crew
MCFARLAND	Completed Dozer Line	Repair Needed	152	Div A and W	1 blade, 1 ft berms Need pulled back + water bar	Excavator
MCFARLAND	Completed Dozer Line	Completed - Inspected	153	Div A and W	2 blades, berms to 4 feet. Berms need knocked down and surface recontoured (tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Completed - Inspected	154	Div A and W	1 blade, berms to 3 ft. Needs barriers where meets road, berms knocked down, and contoured.	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	155	Div A and W	Mostly 1 blade w/ occasional push. Berms relatively small, and previously constructed water bars intact	Excavator to pull berms back, but repair requirements relatively minor. 8/15/21
MCFARLAND	Completed Dozer Line	Repair Needed	156	Div A and W	1-3 blades wide, berms to 3 feet. Needs berms pulled	Excavator
MCFARLAND	Completed Dozer Line	In Progress	157	Div A and W	1-2 blades, berms to 2 feet. Minimal repair needed; pull berms in and water bar where needed	Excavator or Small dozer
MCFARLAND	Completed Dozer Line	Repair Needed	158	Div A and W	1-2 blades, berms to 2 feet. Needs berms pulled back, occasional water bar	Excavator or small dozer
MCFARLAND	Completed Dozer Line	Repair Needed	159	Div A and W	2 blades, 1-2 ft berms need knocked down. (Tfelbeck)	Hand crew
MCFARLAND	Completed Dozer Line	Repair Needed	160	Div A and W	2-5 blades wide, water bars in, need to block at 55 road (high priority)	No equipment on site, water bars in on line but need to block at 55 road
MCFARLAND	Completed Dozer Line	Repair Needed	161	Div A and W	1-2 blades; large berms on sides, moon dust soil,	
MCFARLAND	Completed Dozer Line	Repair Needed	162	Div A and W	1-2 blades assessed by ARCH MJP	
MCFARLAND	Completed Dozer Line	Repair Needed	163	Div A and W	1 blade, green/black. Hose lay still on it. Assessed by arch MJP	Tactical ridgetop repair needed
MCFARLAND	Completed Hand Line	Repair Needed	164	Div A and W	Will need repair, punch out berm on downhill side	
MCFARLAND	Completed Dozer Line	Repair Needed	165	Div A and W	1 blade in drainage	
MCFARLAND	Completed Dozer Line	Repair Needed	166	Div A and W	1 blade assessed by ARCH MJP	Tactical ridgetop repair needed
MCFARLAND	Completed Dozer Line	Repair Needed	167	Div A and W	1 blade, more above	
MCFARLAND	Completed Road as Line	Repair Needed	168	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	169	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	170	Div A and W		Needs to be mapped beyond this area
MCFARLAND	Completed Dozer Line	Repair Needed	171	Div A and W	1-2 blades wide, short loop creating island. READ D.	
MCFARLAND	Completed Dozer Line	Repair Needed	172	Div A and W	Dozer line, 2-5 blades wide. Berms, lots of fuel	Excavator recommended, possibly dozer since grade isn't incredibly

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Repair Needed	173	Div A and W	Dozer line 1-3 blades wide, lots of soil movement and some fuels accumulation on berms. READ D. Plummer	Slope topography too steep for dozer in most areas, repair with excavator.
MCFARLAND	Completed Dozer Line	Repair Needed	174	Div I	Parallels rd. Two blades. Minimal berms	
MCFARLAND	Completed Dozer Line	Repair Needed	175	Div I	2 blades, minimal berms. Parallels road	
MCFARLAND	Completed Dozer Line	Repair Needed	176	Div A and W		Dozer line approximately three blades wide, at the top of the bench reaches approximately 1/4 acre dozer push. Heavy fuels in berms, steep line that continues to Highway 36. Potential seed mulch staging area next to Highway and both benches higher up
MCFARLAND	Completed Dozer Line	Repair Needed	177	Div A and W	This road is an on authorized route on the forest transportation map	This dozer line follows an on authorized route Road bed. I need to block access from authorized roads including Highway 36 and 29N64. 2 to 3 and four blades wide throughout. Heavy fuels piled up in berm. Will need to bring back a vegetation to cover widening of road and dozer pushes, and add drainage as a dozer line and not repair as a road. TS 8/27
MCFARLAND	Completed Dozer Line	Repair Needed	178	Div A and W	This road is an on authorized route on the forest transportation map	This dozer line follows an on authorized route Road bed. I need to block access from authorized roads including Highway 36 and 29N64. 2 to 3 and four blades wide throughout. Heavy fuels piled up in berm. Ladders fuels present. Will need to bring back a vegetation to cover widening of road and dozer pushes, and add drainage as a dozer line and not repair as a road. TS 8/27
MCFARLAND	Completed Dozer Line	Repair Needed	179	Div A and W		Those are one directly connecting with Highway 36. Block entrance to Highway. Add significant drainage work. Tensional area for seed and mulch plan due to potential weed entry from Highway into dubakella road system
MCFARLAND	Road Repair	Repair Needed	180	Div A and W		Road bladed by dozer. Will need drainage and possibly graded.
MCFARLAND	Completed Dozer Line	Repair Needed	181	Div A and W		Steep dozer line ~3 blades wide that narrows to one blade at bottom of the hill where it connects to Highway 36. Priority to block access from Highway 36 and add drainage so runoff does not affect highway. Heavy fuels piled in berm in several places. TS 8/17
MCFARLAND	Completed Road as Line	Repair Needed	182	Div E and Contingency	2 blades adjacent road. Berms 2 ft. Berms need knocked down	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	183	Div E and Contingency	Owen 8/17	
MCFARLAND	Completed Mixed Construction Line	Repair Needed	184	Div E and Contingency	Mostly 4 blades, berms to 3 feet. Berms need knocked down and surface recontoured. road needs graded.	
MCFARLAND	Completed Dozer Line	Repair Needed	185	Div E and Contingency	4 blades, berms to 3 feet. Needs berms knocked down and contoured	Excavator
MCFARLAND	Completed Hand Line	No Repair Needed	186	Div A and W	No Line at all here. Just an old foot trail. No repair needed. MJP	No need to repair

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Repair Needed	187	Div A and W	Primary line. 2-4 blades wide. Berm and vegetation on	Tactical ridgetop repair needed. Close entry point at road. Water bar
MCFARLAND	Completed Dozer Line	Repair Needed	188	Div A and W	3-4 blades. Berms to 3 feet need pulled back and line needs rehabbed. Fuels accumulation needs bucked and	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	189	Div A and W	4-5 blades wide, berms to 4 feet. Fuels accumulation	
MCFARLAND	Completed Dozer Line	Repair Needed	190	Div A and W	1-5 blades. Berms to 4 ft. Berms need pulled back. Rocky in places; water bars where necessary. Earthen barriers	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	191	Div A and W	1-2 Blade wide. Berms to 4 ft. Resurface and spread veg	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	192	Div A and W	2 blades berms 3ft. Needs barrier	
MCFARLAND	Completed Dozer Line	Repair Needed	193	Div A and W	1 blade berms 2-3ft. Needs berms knocked down and contoured	Excavator
MCFARLAND	Completed Hand Line	Repair Needed	194	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	195	Div A and W	1 blade minimal berms. Needs barrier and berms knocked down (tfelbeck)	
MCFARLAND	Completed Hand Line	Repair Needed	196	Div A and W		
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	197	Div A and W	1-2 Blades. Berms to 3 feet. Need berms knocked down, water bars, earthen barrier (tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	198	Div A and W	1-6 blades. Berms to 3 feet. Needs water bars and berms knocked down (tfelbeck)	
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	199	Div A and W	1 blade. Berms to 3ft need knocked down. Water bars where necessary (tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	200	Div A and W	2 blades minimal berms	
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	201	Div A and W	1-6 blades. Berms to 4 feet. Needs contoured, berms	
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	202	Div A and W	1 blade, berms 1-3 ft. Fuels accumulation. Needs berms knocked down and water bars (tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	203	Div A and W	Mostly 1 blade berms 1-3. Fuels accumulation. Berms need knocked down, fuels scattered, and water bars	Excavator
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	204	Div A and W	1 blade, berms to 2 ft. Berms need knocked down, water bars where needed (Tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	205	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	206	Div A and W	5-6 blades wide. Needs water bars and berms pulled in (tfelbeck)	
MCFARLAND	Completed Dozer Line	Repair Needed	207	Div A and W	3-5 blades wide, berms to 5 ft w significant fuels	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	208	Div A and W	1-2 blades. Berms 1-3 ft. Need berms knocked down (tfelbeck)	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	209	Div A and W	1-6 blades, berms to 3 feet. Need berms knocked down	
MCFARLAND	Completed Dozer Line	Repair Needed	210	Div A and W	6 blades, berms to 4'. Significant fuels accumulations.	Excavator
MCFARLAND	Road Repair	Repair Needed	211	Div A and W	Berms to 2 feet need knocked down or drainage punched	
MCFARLAND	Completed Dozer Line	In Progress	212	Div A and W	1-4 blades, berms to 3 feet. Berms need knocked down	Excavator
MCFARLAND	Completed Dozer Line	Repair Needed	213	Div A and W	1-6 blades, berms 1-3 ft. needs berms knocked down and	

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Repair Needed	214	Div A and W	1-7 blades, berms 1-3 ft. Needs berms knocked down,	Excavator
MCFARLAND	Other	Repair Needed	215	Div A and W	Roadside Timber Salvage opportunity downhill side of	
MCFARLAND	Other	Repair Needed	216	Div A and W	Roadside Timber Salvage opportunity. REAF Klotz	
MCFARLAND	Completed Hand Line	No Repair Needed	217	Div A and W	No Line at all here. Just an old foot trail. No repair needed. MJP	No need to repair
MCFARLAND	Completed Road as Line	Repair Needed	218	Div L		
MCFARLAND	Completed Hand Line	Repair Needed	219	Div I		
MCFARLAND	Completed Dozer Line	Repair Needed	220	Div I		
MCFARLAND	Completed Dozer Line	Repair Needed	221	Div E and Contingency	1-2 blades wide, parallels spur road (most likely used for equipment access). READ D. Plummer 08/20	Excavator for fuels placement
MCFARLAND	Completed Hand Line	Repair Needed	222	Div I		
MCFARLAND	Completed Dozer Line	Repair Needed	223	Div I		
MCFARLAND	Completed Dozer Line	Repair Needed	224	Div E and Contingency		
MCFARLAND	Road Repair	Repair Needed	225	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	226	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	227	Div E and Contingency		Tactical ridgetop repair needed. Line follows road and ridge tops.
MCFARLAND	Completed Dozer Line	Repair Needed	228	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	229	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	230	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	231	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	232	Div E and Contingency		
MCFARLAND	Completed Road as Line	Repair Needed	233	Div I		
MCFARLAND	Completed Dozer Line	Repair Needed	234	Div S		
MCFARLAND	Completed Hand Line	Repair Needed	235	Div I	CalFire GPX	
MCFARLAND	Completed Dozer Line	Repair Needed	236	Div I	CalFire Rueger 8/21	
MCFARLAND	Completed Dozer Line	Repair Needed	237	Div I	CalFire Rueger 8/21	
MCFARLAND	Completed Dozer Line	Repair Needed	238	Div I	CalFire Rueger 8/21	
MCFARLAND	Completed Dozer Line	Repair Needed	239	Div I	CalFire Rueger 8/21	
MCFARLAND	Completed Dozer Line	Repair Needed	240	Div I	CalFire Rueger 8/21	
MCFARLAND	Completed Dozer Line	Repair Needed	241	Div I	CalFire Rueger 8/21	
MCFARLAND	Completed Hand Line	Repair Needed	242	Div S		
MCFARLAND	Completed Dozer Line	Completed - Inspected	243	Div S		
Syd	Completed Hand Line	Repair Needed	244	Div S	0020 on 8/19	
MCFARLAND	Completed Dozer Line	Repair Needed	245	Div E and Contingency	Ops Meeting 08/21	
MCFARLAND	Completed Dozer Line	Repair Needed	246	Div E and Contingency	Ops Meeting 08/21	
MCFARLAND	Completed Dozer Line	Repair Needed	247	Div S		
MCFARLAND	Completed Dozer Line	Repair Needed	248	Div S		Tactical ridgetop repair needed
MCFARLAND	Completed Dozer Line	Repair Needed	249	Div S		Tactical ridgetop repair needed
MCFARLAND	Completed Dozer Line	Repair Needed	250	Div S		
MCFARLAND	Completed Dozer Line	Repair Needed	251	Div S		
MCFARLAND	Completed Dozer Line	Repair Needed	252	Div S		
MCFARLAND	Completed Dozer Line	Repair Needed	253	Div S		Tactical ridgetop repair needed
MCFARLAND	Completed Dozer Line	Repair Needed	254	Div S		
MCFARLAND	Completed Dozer Line	Repair Needed	255	Div A and W	Not precise but reflects general location and extent of	
MCFARLAND	Completed Road as Line	Repair Needed	256	Div A and W	Mostly 1 blade, berms to three feet. Needs berms pulled	Excavator

Incident Name	FC Line Type	Repair Status	Repair Num	Div	Comments	Repair Comments
MCFARLAND	Completed Dozer Line	Repair Needed	257	Div A and W		Likely old line from telephone fire. May be primary ridge to keep
MCFARLAND	Completed Dozer Line	Repair Needed	258	Div A and W	Primary line. 2-4 blades wide. Berm and vegetation on	Close entry point at road. Water bar on steep parts. Pull berm. Pile
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	259	Div A and W		
MCFARLAND	Completed Dozer Line	Completed - Ready for Ir	260	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	261	Div I	Reuger 8/22	
MCFARLAND	Completed Dozer Line	Repair Needed	262	Div I	Reuger 8/22	
MCFARLAND	Completed Dozer Line	Repair Needed	263	Div I	Reuger 8/22	
MCFARLAND	Completed Dozer Line	Repair Needed	264	Div L	Reuger 8/22	
MCFARLAND	Completed Dozer Line	Repair Needed	265	Div I	Reuger 8/22	
MCFARLAND	Completed Dozer Line	Repair Needed	266	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	267	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	268	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	269	Div E and Contingency		
MCFARLAND	Other	Other - See Comments	270	Div E and Contingency	Hose lay unknown length of 1" hose	
MCFARLAND	Completed Dozer Line	Repair Needed	271	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	272	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	273	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	274	Div I	Reuger 8/23	
MCFARLAND	Completed Road as Line	Repair Needed	275	Div I	Reuger 8/23	
MCFARLAND	Completed Road as Line	Repair Needed	276	Div A and W		
MCFARLAND	Completed Dozer Line	Repair Needed	277	Div A and W		line is not slope and crosses several drainages
MCFARLAND	Completed Dozer Line	Repair Needed	278	Div A and W	Dozer line from upper line down to road. REAF Klotz	Needs drainage and block access at road entrance
MCFARLAND	Completed Dozer Line	Repair Needed	279	Div A and W	Small dozer line from top of hill down to road below.	Needs drainage and pile heavies, disperse fines.
MCFARLAND	Completed Dozer Line	Repair Needed	280	Div A and W	Small dozer push off main line. REAF Klotz	Drainage and block access from main dozer line.
MCFARLAND	Completed Dozer Line	Repair Needed	281	Div A and W	Short dozer line between upper and lower road. 1 blade	Needs 1-2 water bars and entrance at both roads blocked.
MCFARLAND	Completed Dozer Line	Repair Needed	282	Div E and Contingency		
MCFARLAND	Completed Dozer Line	Repair Needed	283	Div E and Contingency	Owen 8/17	
MCFARLAND	Completed Dozer Line	Repair Needed	284	Div A and W	CalFire Rueger 8/21	Extremely steep up from DP1 to ridge top. ~One blade wide.