

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Dip Site	Bridge Dip	501	Div A and W	Repair Needed		Bridge Dip	40° 23.317'	-123° 3.791'	Not Cleared
Dip Site	Platina Dip	502	Div E and Contingency	Repair Needed		Platina Dip	40° 22.506'	-122° 53.519'	Not Cleared
Drop Point		1 503	Div A and W	Repair Needed		Drop Point 1	40° 22.965'	-123° 3.039'	Not Cleared
Helispot		5 504	Div I	Repair Needed		ICP HELISPOT	40° 19.072'	-122° 47.980'	Not Cleared
Bridge	Bridge Out	505	Div A and W	Repair Needed		Bridge Out	40° 21.661'	-123° 5.371'	Not Cleared
Drop Point		40 506	Div A and W	Repair Needed	Dozer push off road, area mulched. Connects to three towers road	Drop Point 40	40° 23.742'	-123° 6.064'	Not Cleared
Drop Point		39 507	Div A and W	Repair Needed		Drop Point 39	40° 24.050'	-123° 8.079'	Not Cleared
Value at Risk	Cal Trans Yard	508	Div E and Contingency	Repair Needed		Commercial building. >100' clearance.	40° 21.603'	-122° 53.472'	Not Cleared
Value at Risk		509	Div E and Contingency	Repair Needed		1 structure plus 1 outbuilding. No clearance. Just above dry creek bed	40° 21.591'	-122° 53.509'	Not Cleared
Value at Risk		510	Div E and Contingency	Repair Needed		1 structure. Minimal clearance	40° 21.591'	-122° 53.521'	Not Cleared
Value at Risk	4564	511	Div E and Contingency	Repair Needed		1 structure 2 outbuildings	40° 21.585'	-122° 53.534'	Not Cleared
Value at Risk	4560	512	Div E and Contingency	Repair Needed		1 structure	40° 21.587'	-122° 53.538'	Not Cleared
Value at Risk		513	Div E and Contingency	Repair Needed		1 outbuilding (electrical)	40° 21.589'	-122° 53.562'	Not Cleared
Value at Risk		514	Div E and Contingency	Repair Needed		Post office and General Store. 3 buildings total	40° 21.579'	-122° 53.600'	Not Cleared
Value at Risk		515	Div E and Contingency	Repair Needed		1 structure 1 outbuilding	40° 21.568'	-122° 53.547'	Not Cleared
Value at Risk		516	Div E and Contingency	Repair Needed		1 structure 1 outbuilding	40° 21.565'	-122° 53.539'	Not Cleared
Value at Risk		517	Div E and Contingency	Repair Needed		1 structure	40° 21.567'	-122° 53.574'	Not Cleared
Value at Risk		518	Div E and Contingency	Repair Needed		1 structure 1 outbuilding	40° 21.532'	-122° 53.885'	Not Cleared
Value at Risk		519	Div E and Contingency	Repair Needed		1 out building less than 30' clearance. Grass/ timber	40° 21.792'	-122° 54.875'	Not Cleared
Value at Risk		520	Div E and Contingency	Repair Needed		1 outbuilding commercial	40° 21.785'	-122° 54.835'	Not Cleared
Value at Risk		521	Div E and Contingency	Repair Needed		4 outbuildings	40° 21.741'	-122° 54.820'	Not Cleared
Value at Risk		522	Div E and Contingency	Repair Needed		1 occupied structure 100'+ clearance	40° 21.674'	-122° 54.783'	Not Cleared
Value at Risk		523	Div E and Contingency	Repair Needed		3 chicken coups	40° 21.621'	-122° 54.797'	Not Cleared
Value at Risk		524	Div E and Contingency	Repair Needed		1 outbuilding	40° 21.600'	-122° 54.757'	Not Cleared
Value at Risk	2490	525	Div E and Contingency	Repair Needed		Occupied structure	40° 21.505'	-122° 54.940'	Not Cleared
Bridge		526	Div E and Contingency	Unknown		Old Steele bridge	40° 21.446'	-122° 54.947'	Not Cleared
Value at Risk		527	Div E and Contingency	Repair Needed		1 structure. Be advised if entering. Owner very upset and yelling	40° 21.415'	-122° 55.041'	Not Cleared
Value at Risk		528	Div A and W	Repair Needed		4 outbuildings	40° 22.986'	-123° 1.433'	Not Cleared
Value at Risk		529	Div A and W	Repair Needed		8 outbuildings 1 occupied structure	40° 22.948'	-123° 1.392'	Not Cleared
Value at Risk		530	Div A and W	Repair Needed		3 structures	40° 22.986'	-123° 1.539'	Not Cleared
Value at Risk		531	Div A and W	Repair Needed		1 structure	40° 23.055'	-123° 1.891'	Not Cleared
Value at Risk	531	532	Div A and W	Repair Needed		1 structure 1 outbuilding	40° 23.050'	-123° 1.929'	Not Cleared
Value at Risk	551	533	Div A and W	Repair Needed			40° 23.054'	-123° 1.953'	Not Cleared
Value at Risk		534	Div A and W	Repair Needed		1 structure	40° 23.023'	-123° 2.059'	Not Cleared
Value at Risk	681	535	Div A and W	Repair Needed		1 structure	40° 23.085'	-123° 2.087'	Not Cleared
Value at Risk	770	536	Div A and W	Repair Needed		1 structure	40° 23.163'	-123° 2.161'	Not Cleared
Value at Risk	861	537	Div A and W	Repair Needed		1 structure 2 outbuildings	40° 23.098'	-123° 2.221'	Not Cleared
Value at Risk	940	538	Div A and W	Repair Needed		1 structure	40° 23.150'	-123° 2.324'	Not Cleared
Value at Risk	1041	539	Div A and W	Repair Needed		1 structure	40° 23.112'	-123° 2.423'	Not Cleared
Value at Risk		540	Div A and W	Repair Needed		1 outbuilding	40° 23.268'	-123° 2.644'	Not Cleared
Value at Risk		541	Div A and W	Repair Needed		1 structure	40° 23.449'	-123° 2.849'	Not Cleared
Value at Risk		542	Div A and W	Repair Needed		1 structure	40° 23.833'	-123° 2.988'	Not Cleared
Value at Risk	2481	543	Div A and W	Repair Needed		1 structure	40° 23.903'	-123° 3.430'	Not Cleared

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Value at Risk		544	Div A and W	Repair Needed		7 structures	40° 24.016'	-123° 3.377'	Not Cleared
Value at Risk		545	Div A and W	Repair Needed		1 outbuilding	40° 24.053'	-123° 3.456'	Not Cleared
Value at Risk		546	Div A and W	Repair Needed		1 outbuilding	40° 24.032'	-123° 3.587'	Not Cleared
Value at Risk		547	Div A and W	Repair Needed		1 outbuilding	40° 24.024'	-123° 3.568'	Not Cleared
Value at Risk		548	Div A and W	Repair Needed		1 structure, 1 gas pump, 1 propane tank	40° 24.076'	-123° 3.554'	Not Cleared
Value at Risk		549	Div A and W	Repair Needed		4 outbuildings, 1 structure	40° 24.132'	-123° 3.580'	Not Cleared
Value at Risk	3041	550	Div A and W	Repair Needed		1 structure	40° 24.263'	-123° 3.666'	Not Cleared
Value at Risk		551	Div A and W	Repair Needed		1 structure	40° 24.217'	-123° 3.640'	Not Cleared
Value at Risk		552	Div A and W	Repair Needed		4 structures	40° 24.185'	-123° 3.653'	Not Cleared
Value at Risk	3070	553	Div A and W	Repair Needed		1 structure 1 outbuilding	40° 24.302'	-123° 3.617'	Not Cleared
Value at Risk		554	Div A and W	Repair Needed		4 structures, 3 outbuildings	40° 24.343'	-123° 3.651'	Not Cleared
Value at Risk		555	Div A and W	Repair Needed		2 structures, 1 outbuilding	40° 24.370'	-123° 3.659'	Not Cleared
Value at Risk	3170	556	Div A and W	Repair Needed		1 structure	40° 24.375'	-123° 3.648'	Not Cleared
Value at Risk	3381	557	Div A and W	Repair Needed		1 structure	40° 24.427'	-123° 3.675'	Not Cleared
Value at Risk	3620	558	Div A and W	Repair Needed		1 structure, 5 outbuildings	40° 24.742'	-123° 3.612'	Not Cleared
Value at Risk		559	Div A and W	Repair Needed		2 structures, 2 outbuildings	40° 24.801'	-123° 3.607'	Not Cleared
Value at Risk		560	Div A and W	Repair Needed		1 structure	40° 24.819'	-123° 3.627'	Not Cleared
Value at Risk	3751	561	Div A and W	Repair Needed		1 structure	40° 24.872'	-123° 3.607'	Not Cleared
Value at Risk		562	Div A and W	Repair Needed		2 outbuildings, 1 structure	40° 24.900'	-123° 3.501'	Not Cleared
Value at Risk		563	Div A and W	Repair Needed		2 outbuildings	40° 24.904'	-123° 3.536'	Not Cleared
Value at Risk	3841	564	Div A and W	Repair Needed		1 structure, 1 outbuilding	40° 24.923'	-123° 3.524'	Not Cleared
Value at Risk		565	Div A and W	Repair Needed		1 structure	40° 25.058'	-123° 3.395'	Not Cleared
Value at Risk	40500	566	Div A and W	Repair Needed		1 structure	40° 22.847'	-123° 1.639'	Not Cleared
Value at Risk		567	Div A and W	Repair Needed		1 structure	40° 22.756'	-123° 1.891'	Not Cleared
Value at Risk		568	Div A and W	Repair Needed		1 structure	40° 22.811'	-123° 2.046'	Not Cleared
Value at Risk		569	Div A and W	Repair Needed		4 outbuildings, 1 structure	40° 23.329'	-123° 3.521'	Not Cleared
Value at Risk		570	Div A and W	Repair Needed		1 structure, 5 outbuildings	40° 25.205'	-123° 12.938'	Not Cleared
Value at Risk		571	Div A and W	Repair Needed		1 structure	40° 25.164'	-123° 12.910'	Not Cleared
Value at Risk		572	Div A and W	Repair Needed		1 structure	40° 25.189'	-123° 12.856'	Not Cleared
Value at Risk		573	Div A and W	Repair Needed		1 structure	40° 25.149'	-123° 12.762'	Not Cleared
Value at Risk		574	Div A and W	Repair Needed	3 outbuildings, 1 structure		40° 25.052'	-123° 12.649'	Not Cleared
Value at Risk		575	Div A and W	Repair Needed		1 structure	40° 24.998'	-123° 12.664'	Not Cleared
Value at Risk		576	Div A and W	Repair Needed		1 structure	40° 25.024'	-123° 12.617'	Not Cleared
Value at Risk		577	Div A and W	Repair Needed		1 structure	40° 24.860'	-123° 12.664'	Not Cleared
Value at Risk		578	Div A and W	Repair Needed		1 structure	40° 24.839'	-123° 12.612'	Not Cleared
Value at Risk		579	Div A and W	Repair Needed		1 structure	40° 24.815'	-123° 12.679'	Not Cleared
Value at Risk		580	Div A and W	Repair Needed		1 structure	40° 24.716'	-123° 12.649'	Not Cleared
Value at Risk		581	Div A and W	Repair Needed		5 outbuildings, 1 structure	40° 24.793'	-123° 12.500'	Not Cleared
Value at Risk		582	Div A and W	Repair Needed		1 structure	40° 24.743'	-123° 12.533'	Not Cleared
Value at Risk		583	Div A and W	Repair Needed		15 outbuildings, 9 structures	40° 24.323'	-123° 12.294'	Not Cleared
Value at Risk		584	Div A and W	Repair Needed		Harrison gulch cemetary	40° 21.967'	-122° 58.279'	Not Cleared
Value at Risk		585	Div A and W	Repair Needed		1 structure 2 outbuildings	40° 21.694'	-122° 58.084'	Not Cleared
Value at Risk	209	586	Div A and W	Repair Needed		1 structure locked gate	40° 21.520'	-122° 57.849'	Not Cleared
Value at Risk	2400	587	Div A and W	Repair Needed		1 structure	40° 21.410'	-122° 57.851'	Not Cleared
Value at Risk	2450	588	Div A and W	Repair Needed		1 structure	40° 21.415'	-122° 57.776'	Not Cleared
Value at Risk		589	Div A and W	Repair Needed		1 outbuilding	40° 21.284'	-122° 57.757'	Not Cleared
Value at Risk		590	Div A and W	Repair Needed		1 structure	40° 21.597'	-122° 59.161'	Not Cleared
Value at Risk		591	Div A and W	Repair Needed		2 structures	40° 21.276'	-122° 59.874'	Not Cleared

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Value at Risk		592	Div A and W	Repair Needed		1 structure, 1 outbuilding	40° 22.229'	-122° 59.268'	Not Cleared
Value at Risk		593	Div A and W	Repair Needed		1 structure	40° 22.269'	-122° 59.321'	Not Cleared
Value at Risk		594	Div A and W	Repair Needed		1 structure	40° 22.293'	-122° 59.274'	Not Cleared
Value at Risk		595	Div A and W	Repair Needed		1 structure, 1 outbuilding	40° 22.538'	-122° 59.716'	Not Cleared
Value at Risk		596	Div A and W	Repair Needed		Road ends. Private through. 2 structures	40° 22.583'	-122° 59.890'	Not Cleared
Resource Location		597	Div A and W	Repair Needed		Progeny site (forest resource area)	40° 21.722'	-122° 59.063'	Not Cleared
Value at Risk	40940	598	Div A and W	Repair Needed		1 structure	40° 22.903'	-123° 1.258'	Not Cleared
Value at Risk		599	Div A and W	Repair Needed		1 structure, 3 outbuildings	40° 22.308'	-123° 1.631'	Not Cleared
Drop Point	4	600	Div A and W	Repair Needed		Drop Point 4	40° 22.065'	-123° 1.410'	Not Cleared
Drop Point	38	601	Div A and W	Repair Needed		Drop Point 38	40° 24.401'	-123° 11.316'	Not Cleared
Drop Point	25	602	Div A and W	Repair Needed		Drop Point 25	40° 17.559'	-123° 4.481'	Not Cleared
Drop Point	15	603	Div A and W	Repair Needed		Drop Point 15- use updated point locstion at intersection of 10 road and 64 road	40° 17.464'	-123° 1.252'	Not Cleared
Drop Point	20	604	Div A and W	Repair Needed	No new disturbance TS 8/14	Drop Point 20	40° 18.460'	-123° 2.304'	Not Cleared
Drop Point	10	605	Div A and W	Repair Needed		Drop Point 10	40° 20.095'	-123° 0.593'	Not Cleared
Drop Point	27	606	Div E and Contingency	Repair Needed		Drop Point 27	40° 19.719'	-122° 50.536'	Not Cleared
Drop Point	29	607	Div E and Contingency	Repair Needed		Drop Point 29	40° 19.142'	-122° 53.056'	Not Cleared
Drop Point	31	608	Div E and Contingency	Repair Needed		Drop Point 31	40° 16.832'	-122° 52.820'	Not Cleared
Drop Point	33	609	Div S	Repair Needed		Drop Point 33	40° 14.491'	-122° 54.054'	Not Cleared
Drop Point	35	610	Div S	Repair Needed		Drop Point 35	40° 12.130'	-122° 55.800'	Not Cleared
Drop Point	37	611	Div A and W	Repair Needed		Drop Point 37	40° 13.785'	-122° 58.497'	Not Cleared
Water Source		612	Div S	Repair Needed			40° 13.903'	-122° 55.824'	Not Cleared
Water Source		613	Div S	Completed - Ready for Inspection			40° 14.151'	-122° 56.908'	Not Cleared
Value at Risk		614	Div E and Contingency	Repair Needed		1 structure	40° 20.910'	-122° 53.933'	Not Cleared
Value at Risk		615	Div E and Contingency	Repair Needed		Herman monastery	40° 20.769'	-122° 54.005'	Not Cleared
Value at Risk		616	Div E and Contingency	Repair Needed		6 structures	40° 20.765'	-122° 54.055'	Not Cleared
Value at Risk		617	Div E and Contingency	Repair Needed		1 structure	40° 18.910'	-122° 52.819'	Not Cleared
Value at Risk		618	Div S	Repair Needed		1 structure. 30' clearance. 1 propane tank. Metal roof, wooden wood walls. Located mid slope. Tight canopy spacing. Prep work required. 2 dozers, 1 crew recommended.	40° 13.895'	-122° 56.738'	Not Cleared
Repair Point		619	Div E and Contingency	Repair Needed		Dozer created pullout. Berms 1-2 feet, some fuels accumulation	40° 19.622'	-122° 55.115'	Not Cleared
Dozer Push		620	Div E and Contingency	Repair Needed		50x 100 feet. Berms 1-3 feet	40° 19.442'	-122° 55.188'	Not Cleared
Dozer Push		621	Div E and Contingency	Repair Needed		Small dozer push 2 blades wideBerms 1-2 feet	40° 19.399'	-122° 55.296'	Not Cleared
Dozer Push		622	Div E and Contingency	Repair Needed		Berms 1-3 feet	40° 19.344'	-122° 55.343'	Not Cleared
Dozer Push		623	Div E and Contingency	Repair Needed		Dozer push both sides of road. Berms 1-3 feet	40° 19.085'	-122° 55.435'	Not Cleared
Dozer Push		624	Div E and Contingency	Repair Needed	Berms need knocked down and area should be brushed over	dozer push, berms 2-3 feet, possible old tank trap	40° 18.979'	-122° 55.552'	Not Cleared
Drop Point	50	625	Div A and W	Repair Needed		Drop Point 50	40° 21.396'	-123° 9.745'	Cleared for Repair
Drop Point	12	626	Div A and W	Repair Needed		Drop Point 12	40° 14.548'	-122° 58.393'	Not Cleared
Drop Point	14	627	Div A and W	Repair Needed		Drop Point 14	40° 17.403'	-122° 59.271'	Not Cleared
Helispot		1	Div A and W	Repair Needed		Helispot 1	40° 14.958'	-122° 57.581'	Not Cleared
Dip Site	Black Rock Dip	629	Div W	Repair Needed			40° 12.740'	-123° 0.250'	Not Cleared

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Other		630	Div A and W	Other - See Comments		Cows; at least 10 head. Commercial group, one black brockle faced cow belled	40° 15.259'	-123° 1.447'	Not Cleared
Structure Wrap		631	Div A and W	Repair Needed	Wrap completed READ D. Plummer 08/09	Wrapped cabin structure (white rock guard station). Sprinkler kit set up, also. Watered by a mark 3 downhill. MJP	40° 15.164'	-123° 1.381'	Not Cleared
Road Repair		632	Div A and W	No Repair Needed		Decommissioned road; repair NOT NEEDED	40° 21.887'	-123° 5.287'	Not Cleared
Dozer Push		633	Div A and W	Repair Needed	100x30 ft staging area and water access point. Compacted soils. Drains directly to stream.		40° 22.908'	-123° 3.077'	Not Cleared
Water Development or Draft Site		634	Div A and W	Repair Needed		Drafting location. Two temporary dams made with tarps and logs.	40° 22.925'	-123° 3.080'	Not Cleared
Dozer Push		635	Div A and W	Repair Needed		30x30 ft at line intersection	40° 22.830'	-123° 3.533'	Not Cleared
Repair Point		636	Div A and W	Repair Needed	6-7 blades of push right off main stage area. Some scattered shrubbery. READ D. Plummer 08/10		40° 20.093'	-123° 0.624'	Not Cleared
Hazard Tree		637	Div A and W	Repair Needed	Tree was bucked and removed from roadway	20" oak tree blocking road. Needs bucked and scattered	40° 20.000'	-123° 0.693'	Not Cleared
Staging Area		638	Div A and W	Repair Needed		Newly opened staging area off hwy36 North of hwy 36, 2pumps, 4 fold tanks, 3 pumpkins 2 fish screens installed on 8/10. CESO3 LALA4 on property by road.	40° 23.734'	-123° 7.404'	Not Cleared
Water Source		639	Div A and W	Repair Needed			40° 23.480'	-123° 3.620'	Not Cleared
Dip Site	Fork Dip	640	Div A and W	Repair Needed			40° 14.744'	-123° 7.694'	Not Cleared
Dozer Push		641	Div A and W	Repair Needed	Excavator	80 by 30 feet. Berms to 4 feet, fuels accumulation. Partially enters creek bed	40° 20.261'	-123° 1.192'	Not Cleared
Dozer Push		642	Div A and W	Repair Needed	Excavator pull berms back, scatter downed trees	30 by 100 feet, berms 3 feet. Fuels accumulation.	40° 20.688'	-123° 0.641'	Not Cleared
Repair Point		643	Div A and W	Repair Needed		Significant Stump hole on edge of road. Hazard	40° 20.218'	-123° 1.123'	Not Cleared
Hazard Tree		644	Div A and W	Repair Needed		12" hanging over road	40° 20.725'	-123° 0.677'	Not Cleared
Hazard Tree		645	Div A and W	Repair Needed	Tree bucked and removed from roadway. REAF D. Plummer 08/11	20" tree blocking roadway, needs bucked up and removal.	40° 19.894'	-123° 0.793'	Not Cleared
Culvert		646	Div A and W	Repair Needed		Culvert knocked out of placement, sitting displaced on the road berm. REAF D. Plummer	40° 19.909'	-123° 0.904'	Not Cleared
Hazard Tree		647	Div A and W	Repair Needed	Tree bucked and removed from roadway	Tree needs bucked up and removed	40° 19.874'	-123° 0.917'	Not Cleared
Hazard Tree		648	Div A and W	Repair Needed	30" tree down across Beegum creek right before campground	Hazard trees in campground (stovepipe). Large tree downed in road before campground	40° 19.903'	-123° 1.068'	Not Cleared
Hazard Tree		649	Div A and W	Repair Needed		Hazard tree leaning across road before N Beegum creek campground	40° 19.896'	-123° 1.010'	Not Cleared
Other		650	Div A and W	Other - See Comments		Hose lay placed alongside road	40° 20.705'	-123° 0.398'	Not Cleared
Staging Area		651	Div A and W	Repair Needed		Stage area with a lot of surrounding dozer push. Will need repair.	40° 19.816'	-123° 1.060'	Not Cleared
Helispot		2	652	Div A and W	Repair Needed	Helispot 2	40° 15.330'	-123° 2.678'	Not Cleared
Dip Site	Swim Dip	653	Div E and Contingency	Repair Needed			40° 17.473'	-122° 55.537'	Not Cleared
Structure Wrap		654	Div E and Contingency	Completed - Ready for Inspection			40° 17.774'	-122° 52.112'	Not Cleared

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Culvert		655	Div A and W	Repair Needed		Drainage weir smashed in dirt berm by road grader. Will need to be replaced.	40° 22.142'	-123° 1.363'	Cleared for Repair
Dozer Push		656	Div A and W	Repair Needed	20ft single blade push		40° 22.344'	-123° 1.000'	Cleared for Repair
Structure Wrap		657	Div A and W	Repair Needed	Remove wrap and staples.	McFarland communications tower	40° 22.373'	-123° 0.976'	Cleared for Repair
Dozer Push		658	Div A and W	Repair Needed		100ft roadside length widened to ~20ft	40° 22.008'	-123° 1.626'	Cleared for Repair
Dozer Push		659	Div A and W	Repair Needed	100x40ft roadside dozer push		40° 21.895'	-123° 1.753'	Cleared for Repair
Other		660	Div A and W	Other - See Comments		Hose lay	40° 21.880'	-123° 1.752'	Not Cleared
Dozer Push		661	Div A and W	Repair Needed			40° 21.851'	-123° 1.990'	Cleared for Repair
Dozer Push		662	Div A and W	Repair Needed		Dozerline to north hose leads north from road	40° 20.157'	-123° 3.997'	Cleared for Repair
Hazard Tree		663	Div A and W	Repair Needed		Large tree down (30") in Old Cold Creek rd. REAF D. Plummer 8/12/21	40° 23.300'	-123° 4.547'	Not Cleared
Other		664	Div A and W	Other - See Comments		Hoses on the slope	40° 23.301'	-123° 6.633'	Not Cleared
Hazard Tree		665	Div A and W	Repair Needed		40" tree downed in road, was on fire as of 08/12. Impassible road.	40° 21.118'	-123° 2.665'	Not Cleared
Other		666	Div A and W	Other - See Comments		Road blocked with red/white taping.	40° 21.543'	-123° 2.881'	Not Cleared
Hazard Tree		667	Div A and W	Repair Needed	30" tree	Tree down in road 41, headed East off main split	40° 20.926'	-123° 2.593'	Not Cleared
Repair Point		668	Div A and W	Repair Needed		Dozer line upslope	40° 20.982'	-123° 2.977'	Not Cleared
Hazard Tree		669	Div A and W	Repair Needed		Tree down in McFarland ridge road, slash on both sides.	40° 20.942'	-123° 3.031'	Not Cleared
Structure Wrap		670	Div A and W	Repair Needed	Remove tape and wrap	Pack station 10' x 10'. Wrapped wooden eaves and sealed holes in metal roof and siding. Scraped vegetation around adjacent 100'x 40' corral	40° 13.824'	-122° 58.745'	Not Cleared
Stream Crossing		671	Div A and W	Repair Needed			40° 21.004'	-122° 59.547'	Not Cleared
Stream Crossing		672	Div A and W	Repair Needed			40° 21.109'	-122° 59.697'	Not Cleared
Stream Crossing		672	Div A and W	Repair Needed	removed pushed trees and sediment from creek bed - REAF Spooner		40° 21.109'	-122° 59.697'	Not Cleared
Dozer Push		673	Div A and W	Repair Needed			40° 21.268'	-122° 59.868'	Not Cleared
Repair Point		674	Div A and W	Repair Needed		A couple isolated dozer pushes, nothing of significant length (20 feet maybe), repair not necessarily needed.	40° 21.961'	-123° 2.991'	Not Cleared
Other		675	Div A and W	Other - See Comments		Old barrel, possibly arch??	40° 21.801'	-123° 2.897'	Not Cleared
Repair Point		676	Div A and W	Repair Needed	Repair may not be needed, not a high-use road	2 short dozer pushes, but a lot of fuels accumulation and tall berms (1-3 feet). READ D. Plummer 08/13	40° 21.789'	-123° 2.890'	Not Cleared
Hazard Tree		677	Div A and W	Repair Needed		Large stovepipe tree	40° 22.188'	-123° 2.430'	Not Cleared
Road Repair		678	Div A and W	Repair Needed		Big fallout hole in the middle of the road. READ D. Plummer	40° 22.342'	-123° 2.620'	Not Cleared
Dozer Push		679	Div A and W	Repair Needed	Pull berm	Small dozer push. 30x30'. MJP	40° 23.314'	-123° 9.253'	Cleared for Repair
Culvert		680	Div A and W	Repair Needed		Culvert smashed by ~30" tree	40° 21.285'	-123° 3.481'	Not Cleared
Dozer Push		681	Div A and W	Repair Needed		100x 40 ft. Berms 2 feet, some fuels accumulation. Tfelbeck	40° 21.400'	-123° 2.484'	Not Cleared
Dozer Push		682	Div A and W	Repair Needed	Excavator	20 x 50 ft. 4 ft berms need pulled back	40° 21.523'	-123° 2.448'	Not Cleared
Dozer Push		683	Div A and W	Repair Needed	Invasive species probable	Dozer push for DP40	40° 23.716'	-123° 6.120'	Cleared for Repair

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Dozer Push		684	Div A and W	Repair Needed	1/4 acre dozed area , newly opened. Adjacent to hwy 36 and connects to dozer line into dubakella. Potential seed and mulch area. Probable area for invasive species entry. Messy, heavy fuels piled into berms creating ladder fuels	High priority for repair when possible	40° 23.727'	-123° 7.431'	Cleared for Repair
Dozer Push		685	Div A and W	Repair Needed	20x30ft area, potential for seed and mulch. Lots of trash left on drop point.		40° 24.075'	-123° 8.064'	Cleared for Repair
Dozer Push		686	Div A and W	Repair Needed	Standard repair. Vegetation coverage and drainage		40° 24.658'	-123° 7.404'	Not Cleared
Dozer Push		687	Div A and W	Repair Needed	Dozer line from August fire crosses road here. Large open area crossed many times by dozers. Will need vegetation cover.		40° 22.914'	-123° 9.636'	Not Cleared
Dozer Push		688	Div A and W	Repair Needed	Large ~1/2 acre dozer push/intersection of road and dozer line. Heavy fuels in large dirt berms around perimeter.		40° 22.060'	-123° 9.576'	Not Cleared
Road Repair		689	Div E and Contingency	Repair Needed	Part off of road damage from before incident traffic, in road damage from incident	Damaged culvert in road, getting worse. Is from this incident activity on the 45 road	40° 19.258'	-122° 52.897'	Not Cleared
Staging Area		690	Div A and W	Repair Needed	1/2 acre open area, half new dozer push. Potential seed and mulch area.		40° 18.619'	-123° 1.672'	Cleared for Repair
Other		691	Div A and W	Other - See Comments		Cat face tree burning likely to block road	40° 18.669'	-123° 2.016'	Not Cleared
Dozer Push		692	Div A and W	Repair Needed		3 blades wide, berms to 3 feet. Needs berms pulled in and earthen barrier constructed to prevent ohv use (tfelbeck)	40° 18.135'	-123° 4.402'	Not Cleared
Road Repair		693	Div A and W	Repair Needed		Large 4x4' stump hole in road (tfelbeck)	40° 19.133'	-123° 6.765'	Not Cleared
Water Source		694	Div S	Repair Needed		Running stream. To utilize, road segment needs to bladed and install gravity feed to fill pumpkin. 081421	40° 12.110'	-122° 56.144'	Not Cleared
Road Repair		695	Div S	Repair Needed		Suppression temp repair of washout. Needs removed after incident. MJP	40° 11.906'	-122° 57.058'	Cleared for Repair
Drop Point	30	696	Div E and Contingency	Repair Needed			40° 17.485'	-122° 52.438'	Not Cleared
Other		697	Div A and W	Other - See Comments		Rust (disease) resistant sugar pine still alive	40° 21.772'	-122° 58.943'	Not Cleared
Stream Crossing		698	Div A and W	Repair Needed	Pull push out of stream.	Road as completed line goes through drainage. REAF Klotz	40° 22.792'	-123° 7.711'	Not Cleared
Other		699	Div A and W	Other - See Comments	Pick up hose Lays	Hose Lays still on ground. REAF Klotz	40° 22.845'	-123° 7.804'	Not Cleared
Dozer Push		700	Div A and W	Repair Needed	Pull back berms	20x40'	40° 20.448'	-123° 4.113'	Not Cleared
Safety Zone		701	Div A and W	Repair Needed	Excavator	Large clearing- 100x 75ft. Needs berms pulled back in. Very rocky (tfelbeck)	40° 18.479'	-123° 3.236'	Not Cleared
Dozer Push		702	Div A and W	Repair Needed		Berms to 3 feet, very rocky	40° 15.848'	-123° 2.596'	Not Cleared
Repair Point		703	Div A and W	Repair Needed		Larges dozer push out	40° 22.648'	-123° 8.882'	Not Cleared
Repair Point		704	Div A and W	Repair Needed		Large area pushed out by dozer, pumpkin & fold tank with plumbing here; Tank and hose removed. MJP	40° 22.737'	-123° 8.768'	Cleared for Repair
Water Development or Draft Site		705	Div S	Repair Needed	Will need pool development removed. MJP	Mark 3 and developed pool provide water to a pumpkin. Fish screens placed 081521. MJP	40° 11.979'	-122° 57.420'	Cleared for Repair

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Water Development or Draft Site		705	Div S	Completed - Inspected	Will need pool development removed. MJP Everything removed from site - REAF Spooner 08/27	Mark 3 and developed pool provide water to a pumpkin. Fish screens placed 081521. MJP	40° 11.979'	-122° 57.420'	Cleared for Repair
Drop Point	26	706	Div A and W	Repair Needed			40° 18.637'	-123° 6.233'	Not Cleared
Drop Point	24	707	Div A and W	Repair Needed			40° 15.868'	-123° 2.670'	Not Cleared
Road Repair		708	Div A and W	Repair Needed		Fallout in middle of road, currently impassible. READ D. Plummer 08/15	40° 20.191'	-123° 4.104'	Not Cleared
Dozer Push		709	Div A and W	Repair Needed	New push on roadside. Potential start of new line up to top of hill needs to be mapped.		40° 19.210'	-123° 0.536'	Not Cleared
Repair Point		710	Div A and W	Repair Needed		Mess of dozer line below road - needs to be mapped	40° 18.626'	-123° 1.743'	Not Cleared
Repair Point		710	Div A and W	Repair Needed		Mess of dozer line below road - needs to be mapped	40° 18.626'	-123° 1.743'	Not Cleared
Water Development or Draft Site		711	Div A and W	Repair Needed		Developed pooled stream for drafting. Mark 3 and pumpkin set up. MJP	40° 15.066'	-123° 1.463'	Cleared for Repair
Other		712	Div A and W	Other - See Comments		Unused hose and two gated Ys	40° 23.658'	-123° 7.501'	Not Cleared
Dozer Push		713	Div A and W	Repair Needed	5 to 6 blade wide those are push, soft dirt and some heavy fuels in berm.		40° 23.568'	-123° 7.825'	Not Cleared
Dozer Push		714	Div A and W	Repair Needed	Standard repair. Heavy fuels in dirt berm.		40° 23.545'	-123° 7.867'	Not Cleared
Repair Point		715	Div A and W	Repair Needed	Extremely important to block dozer line access from this road.		40° 23.499'	-123° 7.982'	Not Cleared
Dozer Push		716	Div A and W	Repair Needed			40° 23.519'	-123° 7.992'	Not Cleared
Road Repair		717	Div A and W	Repair Needed	Does a line crosses Road, several heavy feels piled up, hose lay buried under Road creating ditch		40° 23.514'	-123° 7.984'	Not Cleared
Dozer Push		718	Div A and W	Repair Needed	Dozer push at intersection of road and dozer line. Cover with vegetation vegetation. Block driving/Ohv access from road into dozer line.		40° 23.598'	-123° 8.259'	Not Cleared
Dozer Push		719	Div A and W	Repair Needed			40° 23.581'	-123° 8.240'	Not Cleared
Clean Up Area		720	Div A and W	Repair Needed	Backhaul needed.	Collapsed pumpkin, porta tank, hose lay, butterflied hose, y valves, and boxes left to pick up. MJP	40° 23.582'	-123° 8.266'	Not Cleared
Dozer Push		721	Div E and Contingency	Repair Needed		70x 30', berms to 3 ft. Fuels accumulation	40° 21.413'	-122° 52.565'	Not Cleared
Staging Area		722	Div I	Repair Needed		From Owen	40° 18.129'	-122° 42.900'	Not Cleared
Drop Point	32	723	Div E and Contingency	Repair Needed			40° 21.562'	-122° 53.630'	Not Cleared
Clean Up Area		724	Div A and W	Repair Needed	Pull hose	Hose running up to a small spot fire to the NE. MJP	40° 21.973'	-123° 9.655'	Cleared for Repair
Clean Up Area		725	Div A and W	Repair Needed	Backhaul needed	One stick of hose on side of Dozerline	40° 22.105'	-123° 9.464'	Cleared for Repair
Clean Up Area		726	Div A and W	Repair Needed		Hose needs back hauled	40° 22.140'	-123° 9.324'	Cleared for Repair
Dozer Push		727	Div A and W	Repair Needed		4 ft berms need pulled back. (Tfelbeck)	40° 15.265'	-123° 0.970'	Not Cleared
Dozer Push		728	Div A and W	Repair Needed	Excavator	50x 30 ft. 1 ft berms and fuels accumulation. Needs berms pulled back, surface contoured, and fuels scattered	40° 15.163'	-123° 0.802'	Not Cleared

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Resource Location		729	Div A and W	Repair Needed	Avoid during repair of the line	Remnants of Dubakella Lookout. MJP	40° 23.036'	-123° 8.781'	
Other		730	Div A and W	Other - See Comments		Roadside salvage potential. REAF Klotz	40° 22.910'	-123° 4.267'	Not Cleared
Dip Site	Yosh Dip	731	Div E and Contigency	Repair Needed			40° 19.835'	-122° 50.865'	Not Cleared
Dip Site	Cabin Dip	732	Div I	Repair Needed			40° 13.957'	-122° 42.640'	Not Cleared
Dip Site	Cow Dip	733	Div L	Repair Needed			40° 10.684'	-122° 36.205'	Not Cleared
Dip Site	Shed Dip	734	Div L	Repair Needed			40° 11.291'	-122° 46.881'	Not Cleared
Structure Wrap		735	Div A and W	Repair Needed		Lookout. Need several ladders- challenging access	40° 23.984'	-122° 57.381'	Not Cleared
Drop Point		60	736	Div S	Repair Needed		40° 8.410'	-122° 49.784'	Not Cleared
Drop Point		28	737	Div L	Repair Needed		40° 10.153'	-122° 47.292'	Not Cleared
Fence - Cut/Damaged		738	Div I	Repair Needed	Fence Repair- 50' One T Post Needed- 3 Stran	CalFire Dawn 8/21	40° 18.823'	-122° 48.648'	
Repair Point		739	Div I	Repair Needed	Ball Rd Repair 1-pull Back Fill Straw Mulch Approaches	CalFire Dawn 8/21	40° 18.767'	-122° 48.593'	
Repair Point		740	Div I	Repair Needed	Excavator Start- Pull Veg	CalFire Dawn 8/21	40° 18.734'	-122° 48.573'	
Dozer Push		741	Div I	Repair Needed	Dozer East Side Likely Needs Waterbared	CalFire Dawn 8/21	40° 17.346'	-122° 48.354'	
Repair Point		742	Div I	Repair Needed	Grader Remove Minor Berm @wcxing	CalFire Dawn 8/21	40° 17.442'	-122° 42.805'	
Fence - Cut/Damaged		743	Div I	Repair Needed	Fence Repair Just Close Both Sections	CalFire Dawn 8/21	40° 16.478'	-122° 42.529'	
Repair Point		744	Div I	Repair Needed	Clean Out Wcxing	CalFire Dawn 8/21	40° 16.467'	-122° 42.532'	
Repair Point		745	Div I	Repair Needed	Clean Out Wcxing	CalFire Dawn 8/21	40° 16.448'	-122° 42.537'	
Culvert		746	Div I	Repair Needed	Clean Out Wcxing- Culvert 1/2 Filled- Existing	CalFire Dawn 8/21	40° 16.393'	-122° 42.539'	
Repair Point		747	Div I	Repair Needed	Clean Out Wcxing	CalFire Dawn 8/21	40° 16.393'	-122° 42.538'	
Fence - Cut/Damaged		748	Div I	Repair Needed	Fence	CalFire Rueger 8/21	40° 18.834'	-122° 49.699'	
Fence - Cut/Damaged		749	Div I	Repair Needed	Fence	CalFire Rueger 8/21	40° 16.837'	-122° 48.519'	
Fence - Cut/Damaged		750	Div I	Repair Needed	Fence	CalFire Rueger 8/21	40° 16.691'	-122° 48.394'	
Fence - Cut/Damaged		751	Div I	Repair Needed	Fence	CalFire Rueger 8/21	40° 17.129'	-122° 48.263'	
Fence - Cut/Damaged		752	Div I	Repair Needed	Fence	CalFire Rueger 8/21	40° 17.984'	-122° 49.013'	
Fence - Cut/Damaged		753	Div I	Repair Needed	Fence	CalFire Rueger 8/21	40° 18.694'	-122° 49.569'	
Fence - Cut/Damaged		754	Div I	Repair Needed	Fence	CalFire Rueger 8/21	40° 18.905'	-122° 49.274'	
Fence - Cut/Damaged		755	Div I	Repair Needed	Gate Repair	CalFire Rueger 8/21	40° 17.413'	-122° 48.780'	
Culvert		756	Div I	Repair Needed	culvert repair	CalFire Rueger 8/21	40° 17.245'	-122° 48.778'	
Road Repair		757	Div I	Repair Needed	Road Work	CalFire Rueger 8/21	40° 16.891'	-122° 48.571'	
Repair Point		758	Div I	Repair Needed	Water Crossing	CalFire Rueger 8/21	40° 18.760'	-122° 48.587'	
Repair Point		759	Div I	Repair Needed	Water Crossing	CalFire Rueger 8/21	40° 17.313'	-122° 48.763'	
Repair Point		760	Div I	Repair Needed	Water Crossing	CalFire Rueger 8/21	40° 17.800'	-122° 48.861'	
Repair Point		761	Div I	Repair Needed	Water Crossing	CalFire Rueger 8/21	40° 18.765'	-122° 48.916'	
Repair Point		762	Div I	Repair Needed	Water Crossing	CalFire Rueger 8/21	40° 18.718'	-122° 48.936'	



FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Repair Point		763	Div I	Repair Needed	Water Crossing	CalFire Rueger 8/21	40° 16.802'	-122° 48.226'	
Water Source		765	Div L	Repair Needed		Ops Meeting 8/21	40° 9.540'	-122° 46.618'	Not Cleared
Water Source		766	Div L	Repair Needed		Ops Meeting 8/21	40° 9.611'	-122° 46.771'	Not Cleared
Water Source		767	Div L	Repair Needed		Wildlife pond on USFS. Recharges overnight. Resource protection area around pond. No ground disturbance allowed. MJP	40° 7.728'	-122° 48.934'	Cleared for Operations
Dozer Push		768	Div S	Completed - Ready for Inspection	Dozer line 3 to 4 width wide, ( in old august complex dozer line) it already has water bars. Their is minimal brush or trees to be pulled in. Up to wilderness boundary		40° 9.587'	-122° 51.240'	Not Cleared
Staging Area		769	Div L	Repair Needed		Dawn Calfire 8/22	40° 10.166'	-122° 47.202'	
Helispot	11	770	Div I	Repair Needed			40° 18.210'	-122° 48.460'	Not Cleared
Fence - Cut/Damaged		771	Div L	Repair Needed		Reuger 8/22	40° 12.168'	-122° 42.430'	
Fence - Cut/Damaged		772	Div I	Repair Needed		Reuger 8/22	40° 19.101'	-122° 49.070'	
Fence - Cut/Damaged		773	Div I	Repair Needed		Reuger 8/22	40° 18.823'	-122° 48.851'	
Fence - Cut/Damaged		774	Div I	Repair Needed		Reuger 8/22	40° 18.822'	-122° 48.913'	
Fence - Cut/Damaged		775	Div I	Repair Needed		Reuger 8/22	40° 17.994'	-122° 47.944'	
Fence - Cut/Damaged		776	Div L	Repair Needed		Reuger 8/22	40° 12.457'	-122° 43.479'	
Fence - Cut/Damaged		777	Div I	Repair Needed		Reuger 8/22	40° 19.009'	-122° 49.109'	
Fence - Cut/Damaged		778	Div I	Repair Needed		Reuger 8/22	40° 19.101'	-122° 49.070'	
Fence - Cut/Damaged		779	Div I	Repair Needed		Reuger 8/22	40° 17.993'	-122° 48.120'	
Fence - Cut/Damaged		780	Div I	Repair Needed		Reuger 8/22	40° 17.333'	-122° 49.281'	
Fence - Cut/Damaged		781	Div L	Repair Needed		Reuger 8/22	40° 12.697'	-122° 43.871'	
Repair Point		782	Div S	Repair Needed	Clean out water crossing	CalFire Rueger 8/23	40° 18.549'	-122° 48.509'	
Repair Point		783	Div L	Repair Needed	Water Bar Steep Areas	CalFire Rueger 8/23	40° 12.583'	-122° 41.443'	
Repair Point		784	Div I	Repair Needed	Minor Soil removal at outlet for ford crossing	CalFire Rueger 8/23	40° 16.541'	-122° 42.560'	
Repair Point		785	Div I	Repair Needed	Remove perched soil above CMP Outlet	CalFire Rueger 8/23	40° 16.808'	-122° 42.632'	
Repair Point		786	Div I	Repair Needed	Remove Soil At CMPoutlet Minor Amt Soil In WC Xing- Smooth Out	CalFire Rueger 8/23	40° 17.077'	-122° 42.701'	
Repair Point		787	Div I	Repair Needed	Remove Soil From Xing Above Road- When Done Close Two Cowboy Gates	CalFire Rueger 8/23	40° 16.541'	-122° 42.560'	
Repair Point		788	Div I	Repair Needed	Remove Soil In Xing -outboard Edge	CalFire Rueger 8/23	40° 16.778'	-122° 42.629'	
Other		789	Div S	Unknown		Hose lay unknown length North and South of dozer line. 1.5 “, with wyes	40° 14.457'	-122° 54.072'	Not Cleared
Other		790	Div S	Unknown	See comments 8/23	200-300;ft of broken 1.5 inch hose up road	40° 14.052'	-122° 54.887'	Not Cleared

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Repair Point		791	Div S	Unknown		Burned up hose. Unknown length wpaxton REAF div s	40° 15.302'	-122° 54.636'	Not Cleared
Repair Point		792	Div S	Unknown	Pick up burned hose and associate debris. Pull rocks across handline and berms south towards dp 33 Type 2 handcrew	Portable tank and handline beginning	40° 14.810'	-122° 53.795'	Not Cleared
Repair Point		793	Div I	Repair Needed	Water Crossing		40° 17.778'	-122° 46.160'	
Fence - Cut/Damaged		794	Div I	Repair Needed	Fence repair		40° 17.990'	-122° 46.460'	
Culvert		795	Div S	Repair Needed		Culvert damage and filled	40° 15.294'	-122° 53.938'	Not Cleared
Resource Location		796	Div S	Repair Needed	Attention to district botanist for evaluation of impacts by suppression and closing of roads and line	Unclear of dozer line impacts	40° 13.019'	-122° 54.767'	Not Cleared
Dozer Push		797	Div S	Completed - Ready for Inspection	See comments . Could use seed and mulch on east side of road	This point represents a larger area and should be depicted as a dozer line that appears to been rehabilitated although not scouted by REAF wpaxton. Water bars put in and no berms appear for 100 yards either direction from main road	40° 10.841'	-122° 50.594'	Not Cleared
Clean Up Area		798	Div S	Repair Needed	8/24 wpaxton	Stashed 14 1 1/2 gated wye 7 nozzles 14 1 1/2 - 1" reducer and multiple sticks of hose	40° 12.726'	-122° 54.820'	Not Cleared
Repair Point		799	Div S	Repair Needed	See above comments	Dp 35 rat rap gap may be difficult to block access. Area is open and would require bringing large boulders to block access to historic Jeep trail. This was used as dozer line and needs some rehab. Sign needs replaced	40° 12.121'	-122° 55.776'	Not Cleared
Resource Location		800	Div S	Unknown	Wpaxton reaf	Sensitive botanical area . Moderate-High severity. Road may be closed due to heavy tree fall 2-5 years	40° 12.784'	-122° 54.397'	Not Cleared
Repair Point		801	Div S	Repair Needed		Powerline needs replacing from power company. REAF Klotz	40° 23.269'	-123° 4.160'	Not Cleared
Other		802	Div S	Repair Needed	Older- block?	Turnaround 75x75 ft	40° 12.701'	-122° 55.671'	Not Cleared
Road Repair		803	Div A and W	Repair Needed		roots burning out under road	40° 20.211'	-123° 1.098'	Cleared for Repair
Road Repair		804	Div A and W	Other - See Comments		roots burning out under road, giant hole	40° 20.228'	-122° 59.779'	Not Cleared
Clean Up Area		805	Div S	Repair Needed	8/27/2021	Spot fire hose lay	40° 13.997'	-122° 54.664'	Not Cleared
Dozer Push		806	Div A and W	Repair Needed	pull soil back into line - REAF Spooner		40° 18.857'	-123° 2.717'	Not Cleared
Stream Crossing		807	Div A and W	Repair Needed	recut bank walls and stream channel and possibly remove down tree. remove excess sediment added from dozer push - REAF Spooner	dozer line across stream, channel has been moderately filled in with pushed sediment and fallen trees. Tree across channel is at least 50in dbh, potential for damming here due to high surrounding slopes. approx 5-7ft channel width No water present	40° 20.151'	-123° 0.624'	

FC Point Type	Label	Repair Num	Division	Repair Status	Repair Comments	Comments	Lat	Long	ARCH Clearance
Stream Crossing		808	Div A and W	Other - See Comments	Remove added sediment piled in stream bed, re-slope channel walls and pack down loose dust. - REAF Spooner	Dozer line across stream channel. General slope of channel still present, more defined than other dozer line xing. meandering channel width of 1-2ft max. No water present (ephemeral stream?)	40° 20.174'	-123° 0.588'	Not Cleared
Repair Point		809	Div A and W	Other - See Comments	fill in hole and compact to stabilize shoulder. inspect for road integrity - Reaf Spooner 08/27	Stump burning out under road - Watch for road undermining. Flagged for mop up	40° 20.702'	-122° 59.380'	Not Cleared
Repair Point		810	Div A and W	Repair Needed	fill in hole and compact ground, stabilize shoulder fill - REAF Spooner 08/27	large 3ft diameter by 2 ft deep burning root system in side of road, address possible road infrastructure issue, slumping of road	40° 18.865'	-123° 1.545'	Not Cleared
Repair Point		811	Div A and W	Repair Needed	inspect road for possible infrastructure damage. fill in hole and compact ground to stabilize shoulder - Reaf Spooner 08/27	Root burn in road bed	40° 18.691'	-123° 1.891'	Not Cleared
Repair Point		812	Div A and W	Repair Needed	put out burn, fill hole and compact material. inspect for road integrity - REAF Spooner 08/27	root burning undermining Road shoulder. large hole 3ft diameter, w approx 2 ft depth in should fill of road, actively burning	40° 18.700'	-123° 1.919'	Not Cleared
Retardant in Avoidance Area		813	Div A and W	Other - See Comments		Retardant dropped in body of water and stream - REAF Spooner	40° 15.263'	-123° 0.886'	Not Cleared
Repair Point		814	Div S	Repair Needed	After that it becomes handline	Repair first 200 ft north up dozer line from Tedoc gap towards Tedoc peak.	40° 14.459'	-122° 54.050'	Not Cleared
Other		815	Div S	Repair Needed		Wilderness sign replacement signage states: "East bow gap (arrow pointing left saddle camp. Arrow right north yolla bolla spring)	40° 10.268'	-122° 53.913'	Not Cleared
Repair Point		816	Div S	Repair Needed		Low cut stumps, cut rounds and spread, camo saw cuts	40° 9.797'	-122° 52.018'	Not Cleared
Repair Point		817	Div S	Repair Needed		2 fell trees need low stumping, tree cut up and rounds spread around. Cameo stumps. Make it look wild again.	40° 9.710'	-122° 51.879'	Not Cleared
Repair Point		818	Div S	Repair Needed		4 to 5 stumps low cut, cameo stumps, make it look wild	40° 9.603'	-122° 51.597'	Not Cleared
Repair Point		819	Div A and W	Unknown		Block dozer line to avoid ohv use	40° 22.720'	-123° 8.736'	Not Cleared
Repair Point		820	Div S	Repair Needed	Tactical Ridgeline needs boulders blocking access from roadbed to dozer line. Photos depict access point from road to dozer. Wpaxton 8/26/21	Block dozer line/ tower road access to ohv. Tedoc tower road block	40° 14.878'	-122° 53.524'	Not Cleared
Repeater	ICP	821	Div I	In Use - Fire Management		Repeatewr at ICP	40° 19.076'	-122° 47.851'	Not Cleared
Repeater	Knob Peak C-5	822	Div A and W	In Use - Fire Management		Repeater on Knob Peak	40° 23.984'	-122° 57.381'	Not Cleared
Repeater	Horse Ridge C-9	823	Div A and W	In Use - Fire Management		Repeater on Horse Ridge	40° 15.787'	-123° 15.788'	Not Cleared
Repeater	Tedoc Mountain C-4	824	Div S	In Use - Fire Management		Repeater on Tedoc Mountain	40° 14.903'	-122° 53.811'	Not Cleared
Repeater	Tomhead C-83	825	Div L	In Use - Fire Management			40° 8.195'	-122° 49.035'	Not Cleared
Resource Location		826	Div S	Repair Needed	No repair until the southern end near Tedoc gap. 300 ft of dozerline that needs rehabilitation	Sensitive botanical area. Tedoc sensitive area	40° 14.802'	-122° 53.808'	Not Cleared