



Repair Status	
● Completed - Inspected	● Completed - Inspected
● Completed - Ready for Inspection	● Completed - Ready for Inspection
● In Progress	● In Progress
● Repair Needed	● Repair Needed
● No Repair Needed	● No Repair Needed
● Other - See Comments	● Other - See Comments
● Unknown	● Unknown

Suppression Repair
Monument
CA-SHF-001187
09/23/2021

- Aerial Hazard
- Check Point
- Dip Site
- Mobile Reliant Base
- Helipad
- Helibase
- Unimproved Landing Area
- Division Break
- Branch Break
- Drop Point
- Camp
- Lookout
- Hot Spot - Spot Fire
- Value at Risk
- Other
- Gate
- Fire Station
- Bridge
- Water Development or Draft Site
- Stream Crossing
- Road Repair
- Retardant in Avoidance Area
- Resource Location
- Repair Point
- Landing or Log Deck
- Hazard Tree
- Dozer Push
- Culvert
- Mobile Weather Unit
- Internal Access
- Repeater
- Safety Zone
- Hazard
- Water Source
- Restricted Water Source
- Completed Burnout
- Completed Dozer Line
- H - H Completed Hand Line
- M - M Completed Mixed Construction Line
- R - R Completed Road as Line
- Planned Dozer Line
- H - H Planned Hand Line
- R - R Planned Road as Line
- Access or Improved Road
- Other
- Repair Line
- Road Repair
- Retardant Drop
- Fire Edge
- Dozer Line
- Non-FS
- USDA FOREST SERVICE
- Forest Boundary
- Wilderness
- National Wild and Scenic River



NAD 1983 UTM Zone 10N
 0 0.75 1.5 3 Miles
 Scale: 1:41,520 (1 inch equals 1 mile)

SUPPRESSION REPAIR
BRANCH 50
MONUMENT
CA-SHF-001187
09/23/2021



Suppression Repair
Monument
CA-SHF-001187
09/23/2021