


Repair Status	
● Completed - Inspected	▬ Completed - Inspected
● Completed - Ready for Inspection	▬ Completed - Ready for Inspection
● In Progress	▬ In Progress
● Repair Needed	▬ Repair Needed
● No Repair Needed	▬ No Repair Needed
● Other - See Comments	▬ Other - See Comments
● Unknown	▬ Unknown

Check Point	Value at Risk	Clean Up Area	Planned Hand Line
Dip Site	Other	Mobile Weather Unit	Planned Mixed Construction Line
Helispot	Gate	Internet Access	Planned Road as Line
Unimproved Landing Area	Repeater	Safety Zone	Access or Improved Road
Division Break	Water Development or Draft Site	Hazard	Other
Branch Break	Stream Crossing	Water Source	Road Repair
Drop Point	Retardant in Avoidance Area	Completed Burnout	Retardant Drop
Camp	Repair Point	Completed Dozer Line	Contained Line
Staging Area	Landing or Log Deck	Completed Fuel Break	NON-FS
Lookout	Hazard Tree	Forest Boundary	USDA FOREST SERVICE
Hot Spot - Spot Fire	Fence - Cut/Damaged	BLM	National Wild and Scenic River
	Dozer Push	Culvert	



SUPPRESSION REPAIR
BRANCH 40
MONUMENT
CA-SHF-001187
09/28/2021



Suppression Repair
Monument
CA-SHF-001187
09/28/2021