



SUPPRESSION REPAIR BRANCH 40

**MONUMENT
CA-SHF-001187
10/04/2021**

- | | | | |
|---------------------------|-----------------------------------|-------------------------------------|----------------------------------|
| ● Dip Site | ● Other | ◆ Mobile Weather Unit | — Access or Improved Road |
| ● Mobile Retardant Base | ● Water Development or Draft Site | ◆ Internet Access | --- Other |
| ● Helispot | ● Stream Crossing | ◆ Repeater | — Repair Line |
| ○ Unimproved Landing Area | ● Road Repair | ⚠ Hazard | --- Road Repair |
|) Division Break | ● Retardant in Avoidance Area | Ⓜ Water Source | — Forest Boundary |
| Branch Break | ● Resource Location | Ⓜ Completed Burnout | — National Wild and Scenic River |
| ■ Drop Point | ● Repair Point | Ⓜ Completed Dozer Line | — PRIVATE |
| ■ Camp | ● Landing or Log Deck | Ⓜ Completed Fuel Break | — USDA FOREST SERVICE |
| ■ Staging Area | ● Fence - Cut/Damaged | Ⓜ Completed Hand Line | — BLM |
| ■ Lookout | ● Dozer Push | Ⓜ Completed Mixed Construction Line | |
| ● Value at Risk | ● Clean Up Area | Ⓜ Completed Road as Line | |

- | | |
|------------------------------------|------------------------------------|
| Repair Status Point | Repair Status Line |
| ● Completed - Inspected | — Completed - Inspected |
| ● Completed - Ready for Inspection | — Completed - Ready for Inspection |
| ● In Progress | — In Progress |
| ● Repair Needed | — Repair Needed |
| ● Other - See Comments | — No Repair Needed |
| ● Unknown | — Other - See Comments |
| | — Unknown |

NAD 1983 UTM Zone 10N