

# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 133  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:**  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:**

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:** Shrub or timber  
**Defensible Space:** 30 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:** Prep and Defend



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:**  
**Collected Date/Time:**

## TRIAGE CATEGORY

**Defensible, Prep and Hold**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 134  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:** T3/4 Engine  
**Describe Access:** Gravel road

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:**

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:** Shrub or timber  
**Defensible Space:**  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:** Prep and Defend



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:**  
**Collected Date/Time:**

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 135  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:**

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:** Shrub or timber  
**Defensible Space:** 30 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:** Prep and Defend



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:**  
**Collected Date/Time:**

## TRIAGE CATEGORY

**Defensible, Prep and Hold**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 136  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:** T3/4 Engine  
**Describe Access:** Gravel road

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:**

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:** Shrub or timber  
**Defensible Space:** 30 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:** Prep and Defend



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:**  
**Collected Date/Time:**

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 137  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:** 1  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:** T3/4 Engine  
**Describe Access:** Gravel road

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:** Structure now has three side sprinklers and north east side 1"lat for protection. Supply comes off landowner well points and

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:** Shrub or timber  
**Defensible Space:** 30 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:** Cleaned around structure for hazards

**FIRESCOPE Tactics:** Prep and Defend



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Michael Muck  
**Collected Date/Time:** 8/18/2021 3:30:37 PM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 138  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:** T3/4 Engine  
**Describe Access:** Gravel road

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:** Two sprinklers installed around the rear of the house connected to the lay from house to the east. Tested and have great

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:** Shrub or timber  
**Defensible Space:** No defensible space  
**Hazards:** Propane tank

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:** Prep and Defend



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Michael Muck  
**Collected Date/Time:** 8/19/2021 4:00:10 PM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 139  
**Type of Structure:** MixedUse  
**Primary Structures:** 1  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:**  
**Siding Material:**  
**Electrical Power:**  
**Gas to Structure:**  
**Comments:** Club House

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:**  
**Defensible Space:**  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:


**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Jason Miller  
**Collected Date/Time:**

## TRIAGE CATEGORY

**Defensible, Stand Alone**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 140  
**Type of Structure:** MixedUse  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:**  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:**  
**Siding Material:**  
**Electrical Power:**  
**Gas to Structure:**  
**Comments:** Laundry/utility house

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:**  
**Defensible Space:**  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:


**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Jason Miller  
**Collected Date/Time:**

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 141  
**Type of Structure:** MixedUse  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:**  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:**  
**Electrical Power:**  
**Gas to Structure:**  
**Comments:** Hay Barn Tack room

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:**  
**Defensible Space:**  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:**



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Jason Miller  
**Collected Date/Time:**

## TRIAGE CATEGORY

**Non-Defensible, Prep and Leave**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 142  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:**  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:**  
**Siding Material:**  
**Electrical Power:**  
**Gas to Structure:**  
**Comments:** Game barn

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:**  
**Defensible Space:**  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:**


**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Jason Miller  
**Collected Date/Time:**

## TRIAGE CATEGORY

**Defensible, Stand Alone**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 143  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:**  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:**  
**Siding Material:**  
**Electrical Power:**  
**Gas to Structure:**  
**Comments:** Storage shed

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:**  
**Defensible Space:**  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:


**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Jason Miller  
**Collected Date/Time:**

## TRIAGE CATEGORY

**Defensible, Prep and Hold**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 75  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:** T3/4 Engine  
**Describe Access:** Gravel road

## STRUCTURE DETAILS

**Roof Material:**  
**Siding Material:**  
**Electrical Power:**  
**Gas to Structure:**  
**Comments:**

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** No reliable water source nearby  
**Fuel Type:**  
**Defensible Space:**  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:** Prep and Go



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Doug Cole  
**Collected Date/Time:** 8/12/2021 12:03:27 AM

## TRIAGE CATEGORY

**Defensible, Stand Alone**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 76  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:** T3/4 Engine  
**Describe Access:** Gravel. Road

## STRUCTURE DETAILS

**Roof Material:**  
**Siding Material:**  
**Electrical Power:**  
**Gas to Structure:**  
**Comments:**

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:**  
**Defensible Space:**  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:** Prep and Defend


**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Doug Cole  
**Collected Date/Time:** 8/12/2021 12:08:52 AM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 77  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:** T3/4 Engine  
**Describe Access:** Gravel road

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:** Peach Tree cabin

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:** Shrub or timber  
**Defensible Space:** 100 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

**FIRESCOPE Tactics:** Prep and Defend



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Douglas Cole  
**Collected Date/Time:** 8/11/2021 11:47:39 PM

## TRIAGE CATEGORY

**Defensible, Stand Alone**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 78  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Fire resistant- tar, rubberized  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** No  
**Comments:** Cabin #8

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 100 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/15/2021 12:42:26 AM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:** 92520 Hwy 96  
**Assigned Structure Number:** 79  
**Type of Structure:** Residential  
**Primary Structures:** 15  
**Outbuildings:** 3  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:** T3/4 Engine  
**Describe Access:** Improved gravel driveway

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Vinyl  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:**

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:** No  
**Water Supply:** Reliable water source nearby  
**Fuel Type:** Shrub or timber  
**Defensible Space:** 100 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):** 10  
**Mitigation Description:** Some handline needed to protect penstock water source. Sprinklers and pumps set up.

**FIRESCOPE Tactics:** Prep and Go


**Resources Needed to Protect Structure:** Two type 3 engines

## INSPECTION INFORMATION

**Collected By:** Douglas Cole  
**Collected Date/Time:** 8/11/2021 11:14:43 PM

## TRIAGE CATEGORY

**Defensible, Stand Alone**







# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 81  
**Type of Structure:** Outbuilding  
**Primary Structures:** 1  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** No  
**Comments:** Tac shed

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 30 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/14/2021 11:46:35 PM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 82  
**Type of Structure:** Industrial  
**Primary Structures:** 1  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Rock, concrete, metal  
**Electrical Power:** Yes  
**Gas to Structure:** No  
**Comments:** Generator/power house for entire ranch

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:** Yes  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 30 ft treated  
**Hazards:** Diesel tanks and generators

## MITIGATION

**Mitigation Time (in hours):** 1  
**Mitigation Description:** Scratch line

## FIRESCOPE Tactics:


**Resources Needed to Protect Structure:** One sprinkler kit and trunk line, scratched around the sides of the structure. Tested water no contact on open electrical boxes,

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/14/2021 11:49:44 PM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 83  
**Type of Structure:** Industrial  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** No  
**Comments:** Chicken coupe

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:** Yes  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 100 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:


## Resources Needed to Protect Structure:

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/14/2021 11:54:52 PM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 84  
**Type of Structure:** Residential  
**Primary Structures:** 1  
**Outbuildings:**  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:** Farm house

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:** Yes  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 100 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:


**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/14/2021 11:57:03 PM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 85  
**Type of Structure:** Residential  
**Primary Structures:** 1  
**Outbuildings:**  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Fire resistant- tar, rubberized  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:** Employee check-in

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:** Shrub or timber  
**Defensible Space:** 30 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/15/2021 12:00:53 AM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 86  
**Type of Structure:** Outbuilding  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:**  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** No  
**Comments:** Rogers creek cabin

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:** Yes  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 100 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:



## Resources Needed to Protect Structure:

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/15/2021 12:03:12 AM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 87  
**Type of Structure:** Commercial  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Combustible or no roof  
**Siding Material:** Vinyl  
**Electrical Power:**  
**Gas to Structure:**  
**Comments:** Large yurt

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 100 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/15/2021 12:16:15 AM

## TRIAGE CATEGORY

**Defensible, Stand Alone**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 88  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** Yes  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Fire resistant- tar,rubberized  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:** Blue house, now has two side sprinklers that are able to be hooked up to homeowners Large irrigation system lay.

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 100 ft treated  
**Hazards:** Propane tank N/W side of structure

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:


**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/15/2021 12:20:03 AM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 89  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:**  
**Comments:** Southern most garage. Now has two sprinklers and one 3/4 lat for end of lay.

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 30 ft treated  
**Hazards:** Lots of construction Material on the s/e side

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:


**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/15/2021 12:21:55 AM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 90  
**Type of Structure:** Outbuilding  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Fire resistant- tar,rubberized  
**Siding Material:** Wood or open sided  
**Electrical Power:** No  
**Gas to Structure:** No  
**Comments:** Horse stable

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** Less than 30 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/15/2021 12:25:00 AM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**







# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 92  
**Type of Structure:** Commercial  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:**  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Rock, concrete, metal  
**Electrical Power:** Yes  
**Gas to Structure:** No  
**Comments:** Wide span metal truss arena cover

**Safety Zone(s):**  
**Comm With ICP:**  
**Water Supply:**  
**Fuel Type:**  
**Defensible Space:** 30 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:



**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/15/2021 12:33:43 AM

## TRIAGE CATEGORY

**Defensible, Stand Alone**



# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:**  
**Assigned Structure Number:** 93  
**Type of Structure:** Residential  
**Primary Structures:**  
**Outbuildings:**  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:**  
**Describe Access:**

## STRUCTURE DETAILS

**Roof Material:** Noncombustible or not applicable  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Unknown  
**Comments:** Cabin #9

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:**  
**Water Supply:** Reliable water source nearby  
**Fuel Type:**  
**Defensible Space:** 100 ft treated  
**Hazards:**

## MITIGATION

**Mitigation Time (in hours):**  
**Mitigation Description:**

## FIRESCOPE Tactics:


**Resources Needed to Protect Structure:**

## INSPECTION INFORMATION

**Collected By:** Vulcan Fire  
**Collected Date/Time:** 8/15/2021 12:35:40 AM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**





# McCash Fire Structure Triage Assessment

CASRF000651  
August 20, 2021



## LOCATION INFORMATION

**Area:** Marble Mountain Ranch  
**Address:** Marble Mountain ranch  
**Assigned Structure Number:** 94  
**Type of Structure:** MixedUse  
**Primary Structures:** 1  
**Outbuildings:** 1  
**Is the building Occupied?:** No  
**Coordinates (DDM):** ,

## ACCESS

**Access to Site:** T1 Engine  
**Describe Access:** Gravel driveway. South of main residence. Kitchen and laundry house

## STRUCTURE DETAILS

**Roof Material:** Combination of fire resistant and combustible  
**Siding Material:** Wood or open sided  
**Electrical Power:** Yes  
**Gas to Structure:** Yes  
**Comments:** Kitchen, restaurant. Open wood deck in front under tall redwoods. Sprinklers, well watered vegetation surrounding structure.

**Safety Zone(s):** Potential safety zone(s) in area  
**Comm With ICP:** Yes  
**Water Supply:** Pressurized hydrant(s) or fixed sprinkler system  
**Fuel Type:** Shrub or timber  
**Defensible Space:** Less than 30 ft treated  
**Hazards:** Propane tanks for bbq

## MITIGATION

**Mitigation Time (in hours):** 2  
**Mitigation Description:** Rake line around structure. Spray down roof and gutters

**FIRESCOPE Tactics:** Prep and Defend

**Resources Needed to Protect Structure:** 1500 Pumpkin, 2 sprinkler kits

## INSPECTION INFORMATION

**Collected By:** Jason Miller  
**Collected Date/Time:** 8/14/2021 10:48:20 PM

## TRIAGE CATEGORY

**Defensible, Prep and Hold**

