


# Suppression Repair Overview

9/5/2022



**SRF Lightning Complex**  
 CA-SRF-000620  
 9/5/2022  
 41,296 acres  
 IR updated 9/4/2022

- |  |   |  |   |  |
|--|---|--|---|--|
| <p><b>Repair Status Point</b></p> <ul style="list-style-type: none"> <li><span style="color: red;">●</span> In Use - Fire Management</li> <li><span style="color: red;">●</span> Repair Needed</li> <li><span style="color: green;">●</span> Completed - Inspected</li> <li><span style="color: green;">●</span> No Repair Needed</li> <li><span style="color: grey;">●</span> Other - See Comments</li> </ul> | <p><b>Repair Status Line</b></p> <ul style="list-style-type: none"> <li><span style="color: red;">—</span> In Use - Fire Management</li> <li><span style="color: red;">—</span> Needs Assessment</li> <li><span style="color: red;">—</span> Repair Needed</li> <li><span style="color: orange;">—</span> In Progress</li> <li><span style="color: yellow;">—</span> Completed - Ready for Inspection</li> <li><span style="color: green;">—</span> Completed - Inspected</li> <li><span style="color: green;">—</span> No Repair Needed</li> <li><span style="color: grey;">—</span> Other - See Comments</li> <li><span style="color: grey;">—</span> Contained</li> <li><span style="color: grey;">—</span> Uncountained</li> <li><span style="color: red;">—</span> Dip Site</li> <li><span style="color: red;">—</span> Mobile Retardant Base</li> </ul> | <ul style="list-style-type: none"> <li><span style="color: purple;">●</span> Helibase</li> <li><span style="color: purple;">●</span> Helisite</li> <li><span style="color: purple;">●</span> Sling Site</li> <li><span style="color: purple;">●</span> Unimproved Landing Area</li> <li><span style="color: purple;">X</span> Division Break</li> <li><span style="color: purple;">X</span> Incident Command Post</li> <li><span style="color: purple;">X</span> Drop Point</li> <li><span style="color: purple;">X</span> Staging Area</li> <li><span style="color: purple;">X</span> Lockout</li> <li><span style="color: purple;">X</span> Value at Risk</li> <li><span style="color: purple;">X</span> Other</li> <li><span style="color: purple;">X</span> Bridge</li> <li><span style="color: purple;">X</span> Water Development or Draft Site</li> <li><span style="color: purple;">X</span> Structure Wrap</li> </ul> | <ul style="list-style-type: none"> <li><span style="color: green;">●</span> Stream Crossing</li> <li><span style="color: green;">●</span> Road Repair</li> <li><span style="color: green;">●</span> Resource Location</li> <li><span style="color: green;">●</span> Repair Point</li> <li><span style="color: green;">●</span> Landing or Log Deck</li> <li><span style="color: green;">●</span> Hazard Tree</li> <li><span style="color: green;">●</span> Fence - Cut/Damaged</li> <li><span style="color: green;">●</span> Doser Push</li> <li><span style="color: green;">●</span> Culvert</li> <li><span style="color: green;">●</span> Clean Up Area</li> <li><span style="color: green;">●</span> Hazard</li> <li><span style="color: green;">●</span> Water Source</li> <li><span style="color: green;">●</span> Completed Dozer Line</li> </ul> | <ul style="list-style-type: none"> <li><span style="color: purple;">—</span> Completed Fuel Break</li> <li><span style="color: purple;">—</span> Completed Hand Line</li> <li><span style="color: purple;">—</span> Completed Road as Line</li> <li><span style="color: purple;">—</span> Access or Improved Road</li> <li><span style="color: purple;">—</span> Other</li> <li><span style="color: purple;">—</span> Repair Line</li> <li><span style="color: purple;">—</span> Road Repair</li> <li><span style="color: purple;">—</span> Retardant Drop</li> <li><span style="color: purple;">—</span> Wildfire Daily Fire Perimeter</li> <li><span style="color: purple;">—</span> Wild &amp; Scenic Rivers</li> <li><span style="color: purple;">—</span> Wilderness</li> </ul> |
|--|---|--|---|--|



N  
W — E  
S

0 0.5 1 2 Miles

Datum: North American 1983

GIS Updated: 9/5/2022 0606