



Suppression Repair Branch X

9/7/2022



SRF Lightning Complex
 CA-SRF-000620
 9/7/2022
 41,406 acres
 IR updated 9/6/2022

Repair Status Point	Repair Status Line	Other Symbols	Infrastructure
In Use - Fire Management	In Use - Fire Management	Dip Site	Completed Dozer Line
Needs Assessment	Needs Assessment	Mobile Retardant Base	Completed Fuel Break
Repair Needed	Repair Needed	Unimproved Landing Area	Completed Hand Line
In Progress	In Progress	Division Break	Completed Road as Line
Completed - Ready for Inspection	Completed - Ready for Inspection	Drop Point	Access or Improved Road
Completed - Inspected	Completed - Inspected	Staging Area	Other
No Repair Needed	No Repair Needed	Lockup	Future Strategic Fireline
No Repair Needed	No Repair Needed	Value at Risk	Wildfire Daily Fire Perimeter
Other - See Comments	Other - See Comments	Other	Wild & Scenic Rivers
	Contained	Water Development or Draft Site	
		Structure Crossing	
		Stream Crossing	
		Road Repair	
		Repair Point	
		Landing or Log Deck	
		Hazard Tree	
		Dozer Push	
		Culvert	
		Clean Up Area	
		Hazard	
		Water Source	



0 0.5 1 2 Miles
 Datum: North American 1983
 GIS Updated: 9/7/2022 0544