



# Suppression Repair Campbell

9/11/2022



**SRF Lightning Complex**  
 CA-SRF-000620  
 9/11/2022  
 41,540 acres  
 IR updated 9/8/2022

Repair Status Point	Repair Status Line	Other Symbols	Other Symbols
In Use - Fire Management	In Use - Fire Management	Helipoint	Structure Wrap
Needs Assessment	Repair Needed	Helibase	Road Repair
Repair Needed	In Progress	Sling Site	Retardant in Avoidance Area
Completed - Inspected	Completed - Ready for Inspection	Unimproved Landing Area	Resource Location
No Repair Needed	Completed - Inspected	Division Break	Repair Point
Other - See Comments	Other - See Comments	Incident Command Post	Landing or Log Deck
		Drop Point	Hazard Tree
		Staging Area	Fence - Cut/Damaged
		Lookout	Dozer Push
		Value at Risk	Culvert
		Other	Clean Up Area
Contained		Gate	Hazard
Uncontained		Dip Site	Water Source
Bridge		Mobile Retardant Base	
			Completed Dozer Line
			Completed Hand Line
			Completed Road as Line
			Access or Improved Road
			Other
			Repair Line
			Retardant Drop
			Future Strategic Fireline
			Wildfire Daily Fire Perimeter
			Wild & Scenic Rivers
			Wilderness



0 0.5 1 2 Miles  
 Datum: North American 1983  
 GIS Updated: 9/10/2022 2052