


Suppression Repair Ammon


9/15/2022



Repair Summary	Lines (Miles)	Points (Count)
In Use - Fire Management	0.0	0
Needs Assessment	8.6	190
Repair Needed	53.7	68
In Progress	21.9	8
Completed - Ready for Inspection	8.6	0
Completed - Inspected	126.9	47
No Repair Needed	38.7	86
Other - See Comments	0.0	12
% Completed	52.5%	11.4%
% Completed or No Repair Needed	67.4%	40.9%

SRF Lightning Complex
 CA-SRF-000620
 9/15/2022
 41,560 acres
 IR updated 9/12/2022

- Repair Status Point**
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Repair Status Line**
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Contained
- Dip Site
- Mobile Retardant Base
- Hillspot
- Unimproved Landing Area
- X Division Break
- Drop Point
- Staging Area
- Lockup
- Value at Risk
- Other
- Water Development or Draft Site
- Structure Wrapping
- Stream Crossing
- Road Repair
- Repair Point
- Landing or Log Deck
- Hazard Tree
- Dozer Push
- Culvert
- Clean Up Area
- Hazard
- Water Source
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Road as Line
- Access or Improved Road
- Other
- Road Repair
- Future Strategic Finesline
- Wildfire Daily Fire Perimeter
- Wild & Scenic Rivers



0 0.5 1 2 Miles

Datum: North American 1983

GISS Updated: 9/14/2022 2117