


# Suppression Repair Ammon


9/24/2022



Repair Summary	Lines (Miles)	Points (Count)
In Use - Fire Management	0.0	0
Needs Assessment	2.0	86
Repair Needed	23.7	46
In Progress	4.2	1
Completed - Ready for Inspection	2.0	1
Completed - Inspected	176.1	104
No Repair Needed	41.6	155
Other - See Comments	7.3	16
% Completed	69.3%	25.7%
% Completed or No Repair Needed	85.5%	63.6%

**SRF Lightning Complex**  
 CA-SRF-000620  
 9/24/2022  
 41,593 acres  
 IR updated 9/22/2022

- Repair Status Point**
- Needs Assessment
  - Repair Needed
  - Completed - Inspected
  - No Repair Needed
  - Other - See Comments
- Repair Status Line**
- In Use - Fire Management
  - Needs Assessment
  - Repair Needed
  - In Progress
  - Completed - Ready for Inspection
  - Completed - Inspected
  - No Repair Needed
  - Other - See Comments
- Drop Point**
- Staging Area
  - Lookout
  - Value at Risk
  - Other
  - Water Development or Draft Site
  - Structure Wrap
  - Stream Crossing
  - Road Repair
  - Repair Point
  - Landing or Log Deck
  - Hazard Tree
  - Dozer Push
  - Culvert
  - Clean Up Area
- Hazard**
- Water Source
  - Completed Dozer Line
  - Completed Fuel Break
  - Completed Hand Line
  - Completed Road as Line
  - Access or Improved Road
  - Road Repair
  - Future Strategic Fireline
  - Wildfire Daily Fire Perimeter
  - Wild & Scenic Rivers



0 0.5 1 2 Miles  
 Datum: North American 1983  
 GIS Updated: 9/23/2022 2023