


Suppression Repair Ammon

9/28/2022



Repair Summary	Lines (Miles)	Points (Count)
In Use - Fire Management	0.0	0
Needs Assessment	2.0	86
Repair Needed	16.0	44
In Progress	3.7	1
Completed - Ready for Inspection	2.0	0
Completed - Inspected	191.3	106
No Repair Needed	41.6	218
Other - See Comments	7.3	16
% Completed	73.3%	22.5%
% Completed or No Repair Needed	89.0%	68.8%

SRF Lightning Complex
 CA-SRF-000620
 9/28/2022
 41,596 acres
 IR updated 9/24/2022

- Repair Status Point**
- Needs Assessment
 - Repair Needed
 - Completed - Inspected
 - No Repair Needed
 - Other - See Comments
- Repair Status Line**
- In Use - Fire Management
 - Needs Assessment
 - Repair Needed
 - In Progress
 - Completed - Ready for Inspection
 - Completed - Inspected
 - No Repair Needed
 - Other - See Comments
- Drop Point**
- Staging Area
 - Lookout
 - Value at Risk
 - Other
 - Water Development or Draft Site
 - Structure Wrap
 - Stream Crossing
 - Road Repair
 - Repair Point
 - Landing or Log Deck
 - Hazard Tree
 - Dozer Push
 - Culvert
- Other**
- Clean Up Area
 - Hazard
 - Water Source
 - Completed Dozer Line
 - Completed Fuel Break
 - Completed Hand Line
 - Completed Road as Line
 - Access or Improved Road
 - Other
 - Road Repair
 - Future Strategic Fireline
 - Wildfire Daily Fire Perimeter
 - Wild & Scenic Rivers

Datum: North American 1983
 GISS Updated: 9/28/2022 0002