


Suppression Repair Ammon

9/29/2022



Repair Summary		Lines (Miles)	Points (Count)
In Use - Fire Management		0.0	0
Needs Assessment		2.0	85
Repair Needed		16.0	37
In Progress		1.7	1
Completed - Ready for Inspection		2.0	0
Completed - Inspected		191.3	111
No Repair Needed		41.6	220
Other - See Comments		7.3	13
% Completed		73.3%	23.6%
% Completed or No Repair Needed		89.0%	70.3%

SRF Lightning Complex

CA-SRF-000620
9/29/2022

41,596 acres
IR updated 9/24/2022

- Repair Status Point**
- Needs Assessment
 - Repair Needed
 - Completed - Inspected
 - No Repair Needed
 - Other - See Comments
- Repair Status Line**
- In Use - Fire Management
 - Needs Assessment
 - Repair Needed
 - In Progress
 - Completed - Ready for Inspection
 - Completed - Inspected
 - No Repair Needed
 - Other - See Comments
 - Contained
 - Dip Site
 - Hellspot
 - Unimproved Landing Area
- Drop Point**
- Drop Point
 - Staging Area
 - Lookout
 - Value at Risk
 - Other
 - Water Development or Draft Site
 - Structure Wrap
 - Stream Crossing
 - Road Repair
 - Repair Point
 - Landing or Log Deck
 - Hazard Tree
 - Dozer Push
 - Culvert
- Other**
- Clean Up Area
 - Hazard
 - Water Source
 - Completed Dozer Line
 - Completed Fuel Break
 - Completed Hand Line
 - Completed Road as Line
 - Access or Improved Road
 - Other
 - Road Repair
 - Future Strategic Fireline
 - Wildfire Daily Fire Perimeter
 - Wild & Scenic Rivers

Datum: North American 1983
GISS Updated: 9/28/2022 2317