


# Suppression Repair Ammon

10/5/2022



Repair Summary	Lines (Miles)	Points (Count)
In Use - Fire Management	0.0	0
Needs Assessment	2.0	79
Repair Needed	17.5	33
In Progress	3.7	1
Completed - Ready for Inspection	2.0	0
Completed - Inspected	181.1	120
No Repair Needed	50.6	217
Other - See Comments	7.3	16
% Completed	69.3%	25.8%
% Completed or No Repair Needed	88.5%	72.3%

**SRF Lightning Complex**  
 CA-SRF-000620  
 10/5/2022  
 41,598 acres  
 IR updated 10/1/2022

- Repair Status Point**
- Needs Assessment
  - Repair Needed
  - Completed - Inspected
  - No Repair Needed
  - Other - See Comments
- Repair Status Line**
- In Use - Fire Management
  - Needs Assessment
  - Repair Needed
  - In Progress
  - Completed - Ready for Inspection
  - Completed - Inspected
  - No Repair Needed
  - Other - See Comments
  - Contained
  - Dip Site
  - Hellspot
  - Unimproved Landing Area
- Drop Point**
- Drop Point
  - Staging Area
  - Lookout
  - Value at Risk
  - Other
  - Water Development or Draft Site
  - Structure Wrap
  - Stream Crossing
  - Road Repair
  - Repair Point
  - Landing or Log Deck
  - Hazard Tree
  - Dozer Push
  - Culvert
- Other**
- Clean Up Area
  - Hazard
  - Water Source
  - Completed Dozer Line
  - Completed Fuel Break
  - Completed Hand Line
  - Completed Road as Line
  - Access or Improved Road
  - Other
  - Road Repair
  - Future Strategic Fireline
  - Wildfire Daily Fire Perimeter
  - Wild & Scenic Rivers

Datum: North American 1983  
 GISS Updated: 10/5/2022 06:39