



SUPPRESSION REPAIR
MOSQUITO
 10/9/2022

<ul style="list-style-type: none"> Wildfire Daily Fire Perimeter Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line Access or Improved Road Repair Line Road Repair 	<ul style="list-style-type: none"> Contained Fire Edge Uncontained Fire Edge Dip Site Helispot Sling Site Division Break Branch Break Drop Point Camp 	<ul style="list-style-type: none"> Staging Area Hot Spot - Spot Fire Value at Risk Gate Water Development or Draft Site Structure Wrap Stream Crossing Road Repair Retardant in Avoidance Area Resource Location 	<ul style="list-style-type: none"> Restricted Water Source In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected Other - See Comments DPA 	<ul style="list-style-type: none"> Other - See Comments In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected Other - See Comments DPA 	<ul style="list-style-type: none"> State BLM USFS BOR SPT Tahoe District Primary Highway Paved Roads Dirt (Not Paved)
--	--	--	---	--	---


SUPPRESSION REPAIR
MOSQUITO
 CA-TNF-001371
 10/9/2022




FOREST SERVICE
U.S. DEPARTMENT OF AGRICULTURE



CALIFORNIA FIRE
INCIDENT MANAGEMENT
TEAM 12
"Adapt, Innovate, and Overcome"





0 3 Miles

NAD83 UTM 11N 1:27,500

Prepared by: CAIIMT2 10/9/2022 10:47

SUPPRESSION REPAIR
MOSQUITO
 10/9/2022

