





<b>SUPPRESSION REPAIR MOSQUITO</b> 10/11/2022	<b>Repair Status Group</b> In Use - Fire Management Needs Assessment Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected Other - See Comments	Wildfire Daily Fire Perimeter Contained Fire Edge Uncountained Fire Edge Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line Access or Improved Road Repair Line Road Repair Dip Site Helispot Sling Site Division Break Branch Break Drop Point Camp	Staging Area Lookout Hot Spot - Spot Fire Value at Risk Gate Water Development or Draft Site Structure Wrap Stream Crossing Road Repair Retardant in Avoidance Area Resource Location Repair Point Landing or Log Deck Hazard Tree Fence - Cut/ Damaged Dozer Push Culvert Clean Up Area	Safety Zone Hazard Water Source Restricted Water Source SPI Tahoe District SPI Existing Fuel Breaks SPI Camino District Blodgett Forest DPA	<b>Repair Status Group - Stage 2 Needed</b> FSR 213 Stage 2 Needed Stage 2 Needed	<b>SUPPRESSION REPAIR MOSQUITO</b> CA-TNF-001371 10/11/2022	  0 1 2 3 Miles NAD83 UTM 10N 1:60,000	 	<b>SUPPRESSION REPAIR MOSQUITO</b> 10/11/2022
						<b>SUPPRESSION REPAIR MOSQUITO</b> 10/11/2022			