
~





Dip Site
Unimproved Landing A
Division Break

Drop Point

Lookout

Other

Stream Crossing

Road Repair
Repair Point
Landing or Log Deck
Dozer Push

Culvert
Repeater
Water Source

Event Point
Repair Status

In Use - Fire Management

Needs Assessment

Repair Needed

Other - See (

In Progress

Completed - Ready for Inspection

Completed - Inspected

Other - See (

Event Line

Repair Status

In Use - Fire |

Needs Assess

No Repair Needed

Other - See Comments

Event Line

Repair Needed

In Progress

Completed - Ready for Inspection

Repair Status

In Use - Fire Management

Needs Assessment

Needs Assessment

Other - See Comments

