







Lookout

Stream Crossing Road Repair Repair Point

Landing or Log Deck Dozer Push Culvert

internet Access Repeater Water Source

Event Point Repair Status In Use - Fire Management Needs Assessment

In Progress Completed - Inspected No Repair Needed

Other - See Comments Event Line Completed - Ready for Inspection Repair Status In Use - Fire Management Needs Assessment

Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments

