

- Dip Site
- Helispot
- Unimproved Landing Area

- Division Break
- Drop Point
- Lookout

- Other
- Water Crossing or Draft Site
- Stream Repair
- Road Repair
- Repair Point

- Landing or Log Deck
- Fence - Cut/Damaged
- Dozer Push
- Culvert


- Clean Up Area
- Internet Access
- Repeater
- Water Source

- Event Point
- Repair Status
- In Use - Fire Management
- Needs Assessment

- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed

- Other - See Comments
- Event Line
- In Use - Fire Management
- Needs Assessment

- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments



Datum: NAD 1983 UTM Zone 10N