






	Dip Site		Division Break		Other		Event Point		Repair Needed		Other - See Comments
	Heliport		Drop Point		Water Crossing or Draft Site		In Progress		Repair Needed		In Progress
	Unimproved Landing Area		Lookout		Stream Repair		Completed - Ready for Inspection		Completed - Ready for Inspection		Completed - Inspected
	Landing or Log Deck		Internet Access		Road Repair		No Repair Needed		No Repair Needed		No Repair Needed
	Fence - Cut/Damaged		Repeater		Repair Point		In Use - Fire Management		In Use - Fire Management		In Use - Fire Management
	Dozer Push		Water Source		Needs Assessment		Needs Assessment		Needs Assessment		Needs Assessment
	Culvert										

Datum: NAD 1983 UTM Zone 10N