



	Dip Site Helispot Unimproved Landing Area Drop Point Lookout	Other Water Crossing or Draft Site Stream Crossing Road Repair Repair Point	Landing or Log Deck Fence - Cut/Damaged Dozer Push Culvert	Clean Up Area Internet Access Repeater Water Source	Event Point Repair Status In Use - Fire Management Needs Assessment	Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed	Other - See Comments Event Line Repair Status In Use - Fire Management Needs Assessment	Repair Needed In Progress Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments
	0 0.1 0.3 0.6 0.9 1.2 Miles							

Datum: NAD 1983 UTM Zone 10N