
ш

 α





Other Property

Pump

Water Tank

Dip Site

Helispot

Unimproved Landing Area

0.6

0.9

1.2

Division Break

Drop Point

Lookout

Other

Water Development or Draft Site

Stream Crossing

Road Repair
Retardant in Avoidance Area
Repair Point
Landing or Log Deck
Fence - Cut/Damaged
Dozer Push
Culvert

Clean Up Area
Internet Access
Repeater
Water Source
Lake / Pond
Lake / Pond (Intermittent)
Stream / River

Wash
Stream/River
Stream/River Intermittent
Local Roads
Gravel Roads
Dirt Roads
Trails

Event Point
Repair Status

In Use - Fire Management

Needs Assessment

Repair Needed

Other - See Comments

In Progress

Event Line

Completed - Ready for Inspection

Completed - Inspected

No Repair Needed

Other - See Comments

Event Line

Repair Status

In Use - Fire Management

Needs Assessment

Needs Assessment

Repair Needed
In Progress
Completed - Ready for Inspection
Completed - Inspected
No Repair Needed
Other - See Comments

