










































REPAIR PILOT

South Fork Complex September 22, 2023



 	 Pump  Water Tank  Sling Site  Drop Point	 Staging Area  Other  Bridge  Road Repair	 Retardant in Avoidance Area  Repair Point  Landing or Log Deck  Dozer Push	 Internet Access  Hazard  Water Source  Lake / Pond	 Stream/River  Stream/River Intermittent  Local Roads  Dirt Roads  Trails	Repair Status  In Use - Fire Management  Needs Assessment  Repair Needed	 In Progress  Completed - Ready for Inspection  Completed - Inspected  No Repair Needed	 Other - See Comments Repair Status  In Use - Fire Management  Needs Assessment  Repair Needed	 In Progress  Completed - Ready for Inspection  Completed - Inspected  No Repair Needed  Other - See Comments
	 0 0.1 0.1 0.3 0.4 0.6 Miles								



Datum: NAD 1983 UTM Zone 10N