



 	<ul style="list-style-type: none"> Other Property Pump Water Tank Dip Site Division Break Dip Point 	<ul style="list-style-type: none"> Other Water Development or Craft Site Stream Crossing Road Repair Repair Point Landing or Log Deck Dozer Push Culvert Repeater Water Source Lake / Pond Stream/River Stream/River Intermittent Local Roads 	<ul style="list-style-type: none"> Gravel Roads Dirt Roads Trails In Use - Fire Management Needs Assessment Repair Needed 	<ul style="list-style-type: none"> Completed - Inspected No Repair Needed Other - See Comments In Use - Fire Management Needs Assessment Repair Needed In Progress 	<ul style="list-style-type: none"> Completed - Ready for Inspection Completed - Inspected No Repair Needed Other - See Comments In Use - Fire Management Needs Assessment Repair Needed In Progress 	<ul style="list-style-type: none"> Event Point Trails BLM_PLS_Section BLM_PLS_Township Lake / Pond Stream/River 255 High Road



Datum: NAD 1983 UTM Zone 10N