



		<ul style="list-style-type: none">Other PropertyPumpWater TankDip SiteHellspotUnimproved Landing Area	<ul style="list-style-type: none">Division BreakDrop PointLookoutOtherWater Development or Draft Site	<ul style="list-style-type: none">Stream CrossingRoad RepairRetardant in Avoidance AreaRepair PointLanding or Log DeckFence - Cut/Damaged	<ul style="list-style-type: none">Dozer PushCulvertClean Up AreaInternet AccessRepeaterWater Source	<ul style="list-style-type: none">Lake / PondLake / Pond (Intermittent)Stream / RiverWashStream/RiverStream/River IntermittentLocal Roads	<ul style="list-style-type: none">Event PointsRepair StatusTrail Status - Fire ManagementNeeds Assessment	<ul style="list-style-type: none">No Repair NeededOther - See Comments	<ul style="list-style-type: none">Needs AssessmentRepair NeededIn ProgressCompleted - Ready for InspectionCompleted - InspectedOther - See Comments	<p>MULTI_DIRECTION_DEM Value</p> <p>255</p> <p>0</p>		
--	--	--	---	--	--	---	--	---	--	--	--	--

Datum: NAD 1983 UTM Zone 10N