



Legend

- Other Property:** Dip Site, Hellsite, Unimproved Landing Area
- Division Break:** Lookout, Water Development or Draft Site
- Stream Crossing:** Road Repair, Retardant in Avoidance Area, Repair Point, Landing or Log Deck, Fence - Cut/Damaged
- Dozer Push:** Culvert, Clean Up Area, Internet Access, Repeater, Water Source
- Lake / Pond:** Lake / Pond (Intermittent), Stream / River, Wash, Stream/River, Stream/River Intermittent, Local Roads
- Event Points:** Repair Status (Needs Assessment, In Progress, Completed - Ready for Inspection, Completed - Inspected), Fire Management (In Use - Fire Management)
- Repair Status:** No Repair Needed, Other - See Comments, Needs Assessment, Repair Needed, In Progress, Completed - Ready for Inspection, Completed - Inspected, No Repair Needed, Other - See Comments
- Event Line:** Repair Status (In Use - Fire Management)
- MULTI_DIRECTION_DEM Value:** 0 to 255

Datum: NAD 1983 UTM Zone 10N