



Legend

- Other Property**: Dip Site, Hellsite, Unimproved Landing Area
- Division Break**: Lookout, Water Development or Draft Site
- Stream Crossing**: Road Repair, Retardant in Avoidance Area, Repair Point, Landing or Log Deck, Fence - Cut/Damaged
- Dozer Push**: Clean Up Area, Internet Access, Repeater, Water Source
- Lake / Pond**: Lake / Pond (Intermittent), Stream / River, Wash, Stream/River, Stream/River Intermittent, Local Roads
- Event Points**: Repair Status (Needs Assessment, In Progress, Completed - Ready for Inspection, Completed - Inspected), Fire Management (In Use - Fire Management)
- Repair Status**: No Repair Needed, Other - See Comments, Needs Assessment, Repair Needed, In Progress, Completed - Ready for Inspection, Completed - Inspected, No Repair Needed, Other - See Comments
- Event Line**: Repair Status (In Use - Fire Management)
- MULTI_DIRECTION_DEM Value**: 255, 0

Datum: NAD 1983 UTM Zone 10N