



**Legend:**

- Other Property:** Dip Site, Hellsite, Unimproved Landing Area
- Division Break:** Drop Point, Lookout, Water Development or Draft Site
- Stream Crossing:** Road Repair, Retardant in Avoidance Area, Repair Point, Landing or Log Deck, Fence - Cut/Damaged
- Dozer Push:** Culvert, Clean Up Area, Internet Access, Repeater, Water Source
- Lake / Pond:** Lake / Pond (Intermittent), Stream / River, Wash, Stream/River, Stream/River Intermittent, Local Roads
- Event Points:** Repair Status (Fire Management, Needs Assessment)
- Repair Status:** Repair Needed, In Progress, Completed - Ready for Inspection, Completed - Inspected
- Other:** No Repair Needed, Other - See Comments
- Event Line:** Repair Status (In Use - Fire Management, Other - See Comments)
- MULTI\_DIRECTION\_DEM Value:** 255, 0

**Scale:** 0, 0.1, 0.3, 0.6, 0.9, 1.2 Miles

**Datum:** NAD 1983 UTM Zone 10N