



Repair Legend

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Chipping

GIS_S_Misc2	FeatureCategory	LatWGS84_DDM	LongWGS84_DDM	RepairStatus	RepairsNeeded
169	Staging Area	41° 49.587' N	123° 59.458' W	Repair Needed	Standard repair. Consider decompaction and reseeded. REAF This 9/5/pull in berms. pick up glosticks and trash. REAF Jackson 9/12/23
174	Dozer Push	41° 49.415' N	123° 59.612' W	Repair Needed	Pull back soil/root push. REAF This 9/5
1388	Gate	41° 49.588' N	124° 00.164' W	Needs Assessment	Assess if private gate or federal gate.
177	Repair Point	41° 49.404' N	123° 59.726' W	Repair Needed	CRITICAL REPAIR. Dozer covered up stream with soil.. remove soil from channel. REAF Cann 9-12.
155	Other	41° 48.953' N	123° 57.768' W	Repair Needed	block ingress with heavies, create outlet for water drainage to the NW across the rd. RMD 4/26

GIS_S_Misc2	FeatureCategory	RepairStatus	Label	Length/Foot	RepairsNeeded
163	Completed Dozer Line	In Progress		2679	CRITICAL REPAIR. See comments. Private property//spoke to Liason officer about this on 9/14. Passed forward names and contact information. REAF Jackson 9/14
6	Completed Mixed Construction Line	In Progress	Chip	2620	along rd ssm pull in berms, clear debris from culvert, chip slash. RMD 4/26/CRITICAL REPAIR. Leonard 8/25 - Pull berms, water bar in steep areas, pull in slash and debris, repair road to standard, block ingress/egress of dozer y. REAF Cann 9-12-23.
9	Completed Road as Line	Repair Needed	Chip	9943	Pull berms, disperse wash piles, chip
10	Completed Road as Line	Repair Needed	Chip	1440	Pull berms, water bar as needed, chip, block at USFS property line
18	Completed Road as Line	Repair Needed	Chip	3436	Chip vegetation along road. Straw and waddle fill slope on French Hill Road. Pull in material, and Berms on dozer line. Water bar in steep areas. Earth Barrier to block ingress from 17940 to line.
19	Completed Road as Line	Repair Needed	Chip	405	Chipping, pull berms
20	Completed Dozer Line	Repair Needed		238	Water bar, pull berms and slash - standard repair
197	Completed Dozer Line	In Progress		1624	Thin windrows of trees on green side. Thin and scatter jackpots of material. Line will be used as control feature for fuels understory burn.
24	Completed Road as Line	Repair Needed	Chip	7588	Chip, pull out slope berms
61	Completed Road as Line	Repair Needed		1031	CRITICAL REPAIR. Scatter 2' berms//spoke with landowner and dozers covered existing gravel on road. recommend lift of gravel to match existing. REAF Jackson 9/12/23
179	Completed Road as Line	Repair Needed	Chip	1484	Chip vegetation along road. Straw and waddle fill slope on French Hill Road. Pull in material, and Berms on dozer line. Water bar in steep areas. Earth Barrier to block ingress from 17940 to line.
91	Completed Dozer Line	In Progress		450	Pull berms and slash onto line, water bar steep slopes, block ingress/egress. REAF Berg 10/2.
92	Completed Dozer Line	Repair Needed		158	pull berms in and scatter brush.. estimate .5 days for type 2 or 3 excavator. Jackson 9/12/23
93	Completed Road as Line	Repair Needed	Chip	538	lots of slash pushed, recommend chipping or possibly pile and burn. REAF Jackson 9/12/23
94	Completed Road as Line	Repair Needed		2490	rolling down waterbars along rd to facilitate drainage closer to the junction, pull back berms and even out along length of rd RMD 4/26
180	Completed Dozer Line	Needs Assessment		1124	PRIVATE. If authorized by the Forest, repair would include using an excavator to smooth out dozer piles and remove berms. REAF Cann 9-16-23.

■ Drop Point	— Completed Hand Line	— Closed Roads
■ Staging Area	— Completed Mixed Construction Line	— Local Road
● Other	— Completed Road as Line	— 4WD
○ Gate	— Access or Improved Road	— Closed Road
● Repair Point	— Paved Road	— Highway
● Dozer Push	— Gravel Road	— Smith River Cx Wildfire Perimeter
xxxx Completed Dozer Line	— Primitive Road	

SPRING SUPPRESSION REPAIR

Smith River Complex - French Hill Repair Area

94,639 acres as of 11/13/2023
Map Date 05/03/2024

0 0.15 0.3 0.6 Miles
18,000 NAD83 UTM 10N

Smith River Complex
CA-SRF-000968
REPAIR