

**Repair Legend**

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Chipping Needed


GISS_Misc2	FeatureCategory	RepairStatus	RepairsNeeded	Label	Length/Feet
30	Completed Road as Line	Repair Needed	recommend saw crew and chipper for piled vegetation not addressed by masticator; grader expected to add rolling dips on 0831	Chip	4313
31	Completed Road as Line	Repair Needed	pull brush from treeline on green side of road and pile/tarp in open spots on roads edge.		2232
202	Road Repair	Repair Needed	Grading needed REAF KBRADY 5/13/24		30216
GISS_Misc2	FeatureCategory	LatWGS84_DDM	LongWGS84_DDM	RepairStatus	RepairsNeeded
1461	Repair Point	41° 50.184' N	124° 04.098' W	Repair Needed	tank trap, block access
	Closure	41° 49.622' N	124° 04.094' W	Repair Needed	tank trap to block access
	Closure	41° 50.037' N	124° 04.058' W	Repair Needed	berms entrance to line, repair water bar and cover line with slash up 100 yards to where it levels out
	Closure	41° 49.622' N	124° 04.005' W	Repair Needed	tank trap, block access

- Drop Point
- Gravel Road
- - - Closed Road
- ⊠ POC Gate
- Primitive Road
- Highway
- ⊠ Closure
- - - Closed Roads
- Local Connecting Road
- Repair Point
- Local Road
- Paved Road
- 4WD

## SPRING SUPPRESSION REPAIR

### Smith River Complex - Hiouchi Repair Area

94,639 acres as of 11/13/2023  
Map Date 05/17/2024



Smith River Complex  
CA-SRF-000968

# REPAIR