

Repair Legend

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Chipping Needed


GISS_Misc2	Feature/Category	Repair/Status	Repairs/Needed	Label	Length/Feet
30	Completed Road as Line	Repair Needed	recommend saw crew and chipper for piled vegetation not addressed by masticator; grader expected to add rolling dips on 0831	Chip	4313
31	Completed Road as Line	Repair Needed	pull brush from tree line on green side of road and pile/tarp in open spots on roads edge.		2232
202	Road Repair	Repair Needed	Grading needed REAF KBRADY 5/13/24		30216
1461	Repair Point	41° 50.184' N 124° 04.098' W	Repair Needed	tank trap, block access	
	Closure	41° 49.622' N 124° 04.094' W	Repair Needed	tank trap to block access	
	Closure	41° 50.037' N 124° 04.058' W	Repair Needed	berms entrance to line, repair water bar and cover line with slash up 100 yards to where it levels out	
	Closure	41° 49.622' N 124° 04.005' W	Repair Needed	tank trap, block access	

- Drop Point
- Gravel Road
- - - Closed Road
- ⊠ POC Gate
- Primitive Road
- Highway
- ⊠ Closure
- - - Closed Roads
- Local Connecting Road
- Repair Point
- Local Road
- Paved Road
- 4WD

SPRING SUPPRESSION REPAIR

Smith River Complex - Hiouchi Repair Area

94,639 acres as of 11/13/2023
Map Date 05/17/2024



Smith River Complex
CA-SRF-000968

REPAIR

0 0.1 0.2 Miles
1:10,000 NAD83 UTM 10N