



Event Line - Repair Status		Event Point - Repair Status		Strategic Repair Line
	In Use - Fire Management		In Use - Fire Management	
	Needs Assessment		Needs Assessment	
	Repair Needed		Repair Needed	
	In Progress		In Progress	
	Completed - Ready for Inspection		Completed - Ready for Inspection	
	Completed - Inspected		Completed - Inspected	
	No Repair Needed		No Repair Needed	
	Other - See Comments		Other - See Comments	

	SRF Lightning Complex		Completed Road as Line		Closure		Bridge		Water Source
	Neighboring Complex Wildfires		Access or Improved Road		Helispot		Repair Point		Summit, Gap
	Contained Fire Edge		Repair Line		Unimproved Landing Area		Landing or Log Deck		Mine Site
	Uncontained Fire Edge		Road Repair		Value at Risk		Hazard Tree		Cemetery
	Completed Dozer Line		Division Break		Other		Dozer Push		CAMPGROUND
	Completed Hand Line		Drop Point		Gate		Repeater		Administrative Forest Boundary

	Ranger District Boundary		Secondary Highway		Trail
	Private Land within Forest Boundary		Road, Unspecified		Trail
	National Wilderness Area		Paved		
	Wild and Scenic River		Gravel Road		
	Reservation Boundary		Dirt Road		
	Yurok Ownership		Unimproved Road		

N
W E
S

0 0.5 1
Miles

NAD 1983 UTM Zone 10N
Contour Interval 80 Ft.