



Event Line - Repair Status		Event Point - Repair Status		Strategic Repair Line
	In Use - Fire Management		In Use - Fire Management	
	Needs Assessment		Needs Assessment	
	Repair Needed		Repair Needed	
	In Progress		In Progress	
	Completed - Ready for Inspection		Completed - Ready for Inspection	
	Completed - Inspected		Completed - Inspected	
	No Repair Needed		No Repair Needed	
	Other - See Comments		Other - See Comments	

	SRF Lightning Complex		Helispot		Bridge		Hazard		Fire Station / EMS Station		Wild and Scenic River
	Contained Fire Edge		Lookout		Stream Crossing		Summit; Gap		CAMPGROUND		Reservation Boundary
	Uncontained Fire Edge		Value at Risk		Road Repair		Mine Site		Administrative Forest Boundary		Yurok Ownership
	Completed Dozer Line		Other		Repair Point		Ranger District Office		Ranger District Boundary		Secondary Highway
	Completed Hand Line		Landmark		Hazard Tree		Cemetery		Private Land within Forest Boundary		Road, Unspecified
	Completed Road as Line		Gate		Dozer Push		School (K - 12)		National Wilderness Area		Paved
	Access or Improved Road		Fire Station		Culvert		Post Office				Gravel Road
					Gate						
					Closure						