


Lime Complex, Lime Fire Suppression Repair Map CA-SHF-1041

August 19, 2008




IMT Situation Unit
August 18, 2008
2222 Hours

REPAIR FOR LIME FIRE

Note: Symbology has been updated for some of the lines.

- COMPLETED REPAIR
- DO NOT DO PER LANDOWNER
- FS GRADER
- WATER TENDER
- N/A, Mulch
- N/A, Drop Point, No Rehab
- N/A, Safety Zone, Pull in Slash
- N/A, Safety Zone, Waterbar
- Dozer, Parking, Drain Dip
- Dozer, Safety Zone, Pull in Slash
- Dozer, Safety Zone, Recontour
- Excavator, Pull in Slash
- Excavator, N/A, Pull in Slash
- Excavator, N/A, Open Drainage
- Excavator, Parking, Pull in Slash
- Excavator, Safety Zone, Pull in Slash
- Excavator, Safety Zone, Recontour
- Hand, Safety Zone, Mulch
- Dozer, Open Drainage
- Excavator, Block Fireline
- Excavator, Open Drainage
- No Rehab
- Dozer, Pull in Berm
- Dozer, Pull in Slash
- Dozer, Waterbar
- Dozerline
- Excavator, Pull in Berm
- Excavator, Pull in Slash
- Excavator, Waterbar
- Excavator, Pull in fill
- Hand, Mulch
- Hand, Pull in Slash
- Hand, Waterbar
- FS road crew
- N/A, Waterbar
- Waterbar
- Other, Mulch



IA Boundary

1:20,000