



BRANCH V

BRANCH I

Label	FC Point Type *	Comments	LAT	LONG
1	Fence - Cut/Damaged		N33° 45.59639124°	W117° 44.06666442°
2	Fence - Cut/Damaged		N33° 45.52414008°	W117° 44.15246022°
3	Fence - Cut/Damaged		N33° 45.50850762°	W117° 41.05743240°
4	Fence - Cut/Damaged	Broken Gate-Comp Claims	N33° 44.63813232°	W117° 39.21319332°
5	Repair Point	Needs Repair	N33° 44.43953070°	W117° 39.34913106°
6	Fence - Cut/Damaged		N33° 44.54875830°	W117° 39.25437774°
7	Repair Point	Possible excavator use	N33° 45.89000526°	W117° 41.64069498°
8	Road Repair	Road Grading Needed	N33° 44.57674560°	W117° 38.75343636°
9	Fence - Cut/Damaged		N33° 45.43674066°	W117° 44.07870942°
10	Fence - Cut/Damaged		N33° 46.06124112°	W117° 43.73982222°
11	Fence - Cut/Damaged		N33° 46.06918794°	W117° 43.97950302°
12	Fence - Cut/Damaged		N33° 45.15032658°	W117° 40.89523140°
13	Repair Point	Needs FSR	N33° 45.17221098°	W117° 40.97882094°
14	Road Repair		N33° 45.27984564°	W117° 41.00205702°
15	Repair Point	Knock down berms	N33° 45.74471526°	W117° 41.52373770°
16	Repair Point	FSR in this area	N33° 45.62567580°	W117° 41.33198160°
17	Repair Point	Knock down berms	N33° 45.61346502°	W117° 41.26848492°

0 0.25 0.5 Miles 1:18,000

Team 4 GIS 12/6/2020
1813 Hours
NAD 83 Teale Albers

- Drop Point
- Helispot
- ⊕ Incident Command Post
- ⊔ Division Break
- ⊔ Branch Break

- ▬ Uncontrolled Fire Edge
- ▬ Contained Line
- ▬ Completed Dozer Line
- ▬ Completed Hand Line
- ▬ Road as Completed Line

- ▬ Silverado Fire
- Repair Status Point
- In Progress

SUPPRESSION REPAIR
BOND INCIDENT - CA ORC 136890
DECEMBER 7, 2020

SUPP REPAIR BOND INCIDENT DECEMBER 7, 2020