



Label	Feature/Category	Comments	Repair Status	LAI	LONG
1	Fence - Cut/Damaged		Completed - Inspected	N33 45 59639124	W117 41 06266442
2	Fence - Cut/Damaged		Completed - Inspected	N33 45 59639124	W117 41 06266442
3	Fence - Cut/Damaged	6 post 4 string	In Progress	N33 45 5335762	W117 41 05743241
4	Fence - Cut/Damaged	Broken Gate-Comp Claims	In Progress	N33 44 63813222	W117 39 21319332
5	Repair Point	Needs Repair	In Progress	N33 44 43953070	W117 39 34913106
6	Fence - Cut/Damaged		In Progress	N33 44 54879300	W117 39 25437774
7	Repair Point	Possible excavator use	Completed - Inspected	N33 45 89035252	W117 41 04099498
8	Road Repair	Road Grading Needed	In Progress	N33 45 51676561	W117 39 79238389
10	Fence - Cut/Damaged		Completed - Inspected	N33 46 06124112	W117 43 73982222
11	Fence - Cut/Damaged		Completed - Inspected	N33 46 06918741	W117 43 97950302
12	Fence - Cut/Damaged		In Progress	N33 45 15030658	W117 40 89623140
13	Repair Point	Needs FSR	In Progress	N33 45 17221088	W117 40 97983594
14	Road Repair		Completed - Inspected	N33 45 71848564	W117 41 00257072
15	Repair Point	Knock down berms	Completed - Inspected	N33 45 74471526	W117 41 52373707
16	Repair Point	FSR in this area	Completed - Inspected	N33 45 62567680	W117 41 33198160
17	Repair Point	Knock down berms	Completed - Inspected	N33 45 61346602	W117 41 26248492

0 0.25 0.5 Miles 1:18,000

Team 4 GISS  
12/7/2020  
2044 Hours  
NAD 83 Teale Albers

Drop Point
Helispot
Incident Command Post
Division Break
Branch Break

Uncontrolled Fire Edge
Contained Line
Completed Dozer Line
Completed Hand Line
Road as Completed Line

Silverado Fire
Repair Status Point
Completed - Inspected
In Progress

**SUPPRESSION REPAIR**  
BOND INCIDENT - CA ORC 136890  
DECEMBER 8, 2020