


Repair Point	Description
<b>Watercourse Crossing</b>	
1	class iii
2	class iii dozer wing
4	dozer crossing class iii
19	Dozer Thru Class 3
34	Creek crossing push class 3 stream, excavator
<b>Fence</b>	
6	fence repair
7	Cut Fence
8	Cut fence: 5 Wire X 30', 2 T-posts
10	Cut fence
11	Cut fence
12	2 P 45
13	Damaged Fence From Dozer Line-2 Posts 4 Strings
15	Fence Repair-From Dozer Line
16	Fence That Is Damaged- Needed To Contain Livestock
17	Fence- 4 Posts 4 Strings
20	REPAIR: 1p4s Fence Cut
21	REPAIR: 3p5s Fence
25	REPAIR: Fence 1p5s
26	REPAIR: 4s1p
28	4 strands barbed over hog wire direct dozer line goes east 2 blades wide
29	Placemark 11 cut fence
32	5 strand barbed
35	3 strand barb wire 15 feet. Splice in 4 feet per strand
37	Cut Fence 5 Wire X 40', 4 T-posts
38	Fence Dozer
39	Fence 2 P 4 S
40	Fence 3p 3 S
41	Fence 2p 7s
42	Fence 8 P 3 S. 2 Foot Wire Base Fencing
43	Fence. 2 P 6 S
44	Fence. 8 P. 3 S. 2 Foot Wire Base Fencing
46	barb wire fence repair, wire cut
48	REPAIR: 2p4s Cut Fence
49	REPAIR: Cut Fence 1p.4s: Water Line Damaged
50	REPAIR: Cut Fence 1p4s
51	REPAIR: Cut Fence 2p4s
52	REPAIR: Cut Fence Pasture+2, 1p
55	REPAIR: Pasture Fence+2, 1p
56	REPAIR CUT FENCE: Cowboy Gate, 2p (H brace?)
<b>Dozer Push</b>	
5	safety zone clearing w dozer
18	Dozer 2 Pushes Into Class 3 Confluence
22	REPAIR: Dozer Debris Pushes Swale
23	REPAIR: Dozer Push In Class 3
24	REPAIR: Dozer Push In Swale
27	REPAIR: dozer Push Into Swale
45	200 foot dozer push accessed by highblade down ridge
47	REPAIR dozer push On Road
53	REPAIR: Dozer Push Down Deals
54	REPAIR: Dozer Push Into Culvert Inlet
<b>Road Needs Repair</b>	
30	Placemark 13 grousers in runway
<b>Culvert Damage</b>	
3	dig out culvert inlet blocked 12 inch black plastic
31	Placemark 28 buried culvert
<b>Cattleguard Damage</b>	
36	Broken cattle guard
<b>Other</b>	
9	Berms- hand crew work
14	Drainage Blocked By Dozer Line Slough



**SUP REP MAP**  
**RIVER INCIDENT**  
 CA MMU 014714  
 July 16, 2021

**SUPPRESSION REPAIR MAP**  
**RIVER INCIDENT**  
 CA MMU 014714  
 July 16, 2021

Datum: NAD 83

0 1/2 3 6 Miles

**SUPPRESSION REPAIR MAP**  
**RIVER INCIDENT**  
 CA MMU 014714  
 July 16, 2021

- Cattleguard Damage
- Culvert Damage
- Dozer Push
- Fence Damage
- Other
- Road Needs Repair
- Water Course Crossing
- Dip Site
- Division Break
- Branch Break
- Drop Point
- Completed Dozer Line
- Completed Hand Line
- Completed Road as Line
- Planned Dozer Line
- Fire Edge
- Completed Dozer Line
- Wildfire Daily Fire Perimeter



**SUP REP MAP**  
**RIVER INCIDENT**  
 CA MMU 014714  
 July 16, 2021

MT 6.015  
 7/15/2021  
 2222 Miles