




Repair Point	Description
1	Watercourse Crossing
2	class iii
4	dozer crossing class iii
19	Dozer Thru Class 3
34	Creek crossing push class 3 stream, excavator
63	REPAIR: DOZER CROSSED CHINCHILLA RIVER
6	Fence
7	fence repair
8	Cut Fence
10	Cut fence
11	Cut fence
12	2 P 4S
13	Damaged Fence From Dozer Line-2 Posts 4 Strings
15	Fence Repair-From Dozer Line
16	Fence That Is Damaged- Needed To Contain Livestock
17	Fence- 4 Posts 4 Strings
20	REPAIR: 1p4s Fence Cut
21	REPAIR: 3p5s Fence
25	REPAIR: Fence 1p5s
26	REPAIR: 4s1p
28	4 strands barbed over hog wire direct dozer line goes east 2 blades wide
29	Placemark 11 cut fence
32	2 strands barbed over hog wire cut two places approach from west
33	5 strand barbed
35	3 strand barb wire 15 feet. Splice in 4 feet per strand
37	Cut Fence 5 Wire X 40', 4 T-posts
38	Fence Dozer
39	Fence 2 P 4 S
40	Fence 2p 3 S
41	Fence 2p 7s
42	Fence 8 P 3 S. 2 Foot Wire Base Fencing
43	Fence. 2 P 6 S
44	Fence. 8 P 3 S. 2 Foot Wire Base Fencing
46	barb wire fence repair, wire cut
48	REPAIR: 2p4s Cut Fence
49	REPAIR: Cut Fence 1p,4s: Water Line Damaged
50	REPAIR: Cut Fence 1p4s
51	REPAIR: Cut Fence 2p4s
52	REPAIR: Cut Fence Pasture+2, 1p
55	REPAIR: Pasture Fence+2, 1p
56	REPAIR: CUT FENCE: Cowboy Gate, 2p (H brace?)
57	5 wire fence repair,
58	barb wire and gate down, needs repair
59	Fence- 2 P No Strands Broken
60	Fence-4S No Posts
61	REPAIR Cut Fence 1p3s
62	REPAIR Cut Fence 1p4s
64	Fence Line
67	Re-hang gate 5
5	Dozer Push
18	safety zone clearing w dozer
22	Dozer 2 Pushes into Class 3 Confluence
23	REPAIR: Dozer Debris Pushes Swale
24	REPAIR: Dozer Push In Class 3
27	REPAIR: dozer Push Into Swale
45	200 foot dozer push accessed by highblade down ridge
47	REPAIR dozer Push On Road
53	REPAIR: Dozer Push Down Deals
54	REPAIR: Dozer Push Into Culvert Inlet
30	Road Repair
3	Placemark 13 grousers in runway
3	Culvert Damage
31	dig out culvert inlet blocked 12 inch black plastic
67	Placemark 26 buried culvert
36	Dented culvert
36	Cattleguard Damage
36	Broken cattle guard
9	Other
9	Berms- hand crew work
14	Drainage Blocked By Dozer Line Slough









Scale: 1:12,000
Datum: NAD 83

SUPPRESSION REPAIR MAP

RIVER INCIDENT

CA MMU 014714
July 17, 2021



DISCLAIMER:
The displayed incident data is approximate and should only be used for informational purposes. The information contained in supporting base layers was generated from GIS data maintained by different sources and agencies and is not necessarily accurate to mapping, surveying, or engineering standards.

MMF 6 GIS
7/17/2021
0711 Hours

SUP REP MAP
RIVER INCIDENT
CA MMU 014714
July 17, 2021