



- 11% Repair Needed**
 - Dozer Line (2.4 mi)
 - Hand Line (8.6 mi)
 - Road as Line (2.2 mi)
 - Chipping/Mastication (1.3 mi)
- 7% Repair In Progress**
 - Dozer Line (6.6 mi)
 - Hand Line (1.9 mi)
 - Road as Line (0.0 mi)
 - Chipping/Mastication (0.0 mi)
- 82% Repair Approved**
 - Dozer Line (64.3 mi)
 - Hand Line (10.8 mi)
 - Road as Line (20.9 mi)
 - Chipping/Mastication (7.1 mi)

- Cedar Fire
- Contained Fire Edge
- Division Break
- Incident Command Post
- Camp
- Drop Point
- Helibase
- National Forest Boundary
- Private Land within Forest Boundary
- Bureau of Land Management
- Tule River Indian Reservation
- Helispot
- Retardant Pickup
- Dip Site
- Water Source
- RAWS
- Repeater
- Damage

