


| RepairID | FeatureCategory | RepairStatus | RepairComments |
|----------|------------------------|------------------|--------------------------|
| 1 | Uncontrolled Fire Edge | No Repair Needed | |
| 7 | Completed Dozer Line | Repair Needed | |
| 8 | Completed Dozer Line | Repair Needed | |
| 10 | Completed Dozer Line | Repair Needed | |
| 11 | Completed Line | No Repair Needed | |
| 12 | Completed Line | No Repair Needed | |
| 14 | Completed Line | No Repair Needed | |
| 15 | Uncontrolled Fire Edge | No Repair Needed | |
| 16 | Completed Dozer Line | Repair Needed | |
| 17 | Completed Dozer Line | Repair Needed | |
| 18 | Completed Dozer Line | Repair Needed | |
| 19 | Completed Dozer Line | Repair Needed | 2-4 Blades wide |
| 20 | Completed Dozer Line | Repair Needed | |
| 21 | Completed Hand Line | Repair Needed | |
| 22 | Completed Hand Line | Repair Needed | |
| 23 | Completed Hand Line | Repair Needed | |
| 25 | Completed Hand Line | Repair Needed | |
| 26 | Completed Dozer Line | Repair Needed | |
| 27 | Completed Dozer Line | Repair Needed | Large clearing at center |
| 28 | Completed Dozer Line | Repair Needed | |

| Label | FeatureCategory | RepairStatus | RepairComments |
|-------|-----------------|------------------|---|
| DIV O | Division Break | No Repair Needed | |
| DIV A | Division Break | No Repair Needed | |
| DIV M | Division Break | No Repair Needed | |
| DIV Z | Division Break | No Repair Needed | |
| DP-3 | Drop Point | Unknown | |
| DP-2 | Drop Point | Unknown | |
| DP-1 | Drop Point | Unknown | |
| 1 | Dip Site | Unknown | |
| FENCE | Other | Repair Needed | Fence- 100' 4-wire barbed replace w/ metal stakes |



SUPPRESSION REPAIR

Front Incident

CA-LPF-002334

August 23, 2018

| | | | | | |
|--|--|--|------------------|--|------------------|
| | | | No Repair Needed | | No Repair Needed |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

1:12,000
NAD 1983 UTM Zone 10N

FRONT
CA-LPF-002334
SUP REP
August 23, 2018